



Overview: Part of spill impact on 4" Imo River Well55S flowline right of way at Igiriukwu. Picture was taken during Joint Investigation of 31st July 2013.



Close up: Hacksaw cut on 4" Imo River Well55S flowline at Igiriukwu. Picture was taken during Joint Investigation of 31st July 2013.