



Overview: Part of spill impact on 20" Rumuekpe-Nkpoku pipeline right of way at Ibaa. Picture was taken during Joint Investigation of 12<sup>th</sup> July 2013.



Close up: Drilled hole before plugging on 20" Rumuekpe-Nkpoku pipeline at Ibaa. Picture was taken during Joint Investigation of 12<sup>th</sup> July 2013.



Close up: Drilled hole plugged with a wooden peg on 20" Rumuekpe-Nkpoku pipeline at Ibaa. Picture was taken during Joint Investigation of 12<sup>th</sup> July 2013.