





Overview: Part of spill impact on Ahia Well 3S Flowline at Egbeda. Picture was taken during Joint Investigation of 19<sup>th</sup> July 2016.



Close-up: Hack Saw Cut on Ahia Well 3S Flowline at Egbeda. Picture was taken during Joint Investigation of 19<sup>th</sup> July 2016.



Overview: Part of spill impact on Ahia Well 3S Flowline at Egbeda. Picture was taken during Joint Investigation of 19<sup>th</sup> July 2016.



Close-up: Part of Missing Flowline on Ahia Well 3S Flowline at Egbeda. Picture was taken during Joint Investigation of 19<sup>th</sup> July 2016.