



Overview: Part of spill impact on Imo River 3 Well 22S Flowline Right of Way at Igiriukwu-Owaza. Picture was taken during Joint Investigation of 20th July 2017.



Close-up: Hacksaw Cut on Imo River 3 Well 22S Flowline at Igiriukwu-Owaza. Picture was taken during Joint Investigation of 20th July 2017.