




Overview: Part of spill impact on Imo River Well 33 at IpuWest-Owaza. Picture was taken during Joint Investigation of 31<sup>st</sup> July 2019.



Close-up: Tampered Valves on Imo River Well 33 at IpuWest-Owaza. Picture was taken during Joint Investigation of 31<sup>st</sup> July 2019