



Overview: Part of the spill impact on Cawthorne channel Well 45T flowline at Mbiama.  
Picture taken during Joint Investigation of 23<sup>rd</sup> June, 2011



Close-up: Spill point due to corrosion on Cawthorne channel Well 45T flowline at Mbiama.  
Picture taken during Joint Investigation of 23<sup>rd</sup> June, 2011