



Overview: Part of spill impact on 6" bulkline to Agbada2 flowstation at Agbada. Picture taken during Joint Investigation of 20th June, 2011



Close-up: Spill from pinhole due to corrosion on 6" bulkline to Agbada2 flowstation at Agbada. Picture taken during Joint Investigation of 20th June, 2011