



Overview: Part of spill impact on 12" ImoRiver2 pipeline at Odagwa. Picture taken during Joint Investigation of 17th June, 2011



Close-up: Illegally welded fitting on 12" ImoRiver2 pipeline at Odagwa. Picture taken during Joint Investigation of 17th June, 2011



Close-up: Illegally welded fittings on 12" ImoRiver2 pipeline at Odagwa. Picture taken during Joint Investigation of 18th June, 2011



Close-up: Illegally welded fitting on 12" ImoRiver2 pipeline at Odagwa. Picture taken during Joint Investigation of 18th June, 2011



Close-up: Illegally welded fitting on 12" ImoRiver2 pipeline at Odagwa. Picture taken during Joint Investigation of 18th June, 2011