



Overview: Part of spill impact on 24" Nkpoku-Boma pipeline at Akpajo. Picture taken during Joint Investigation of 17<sup>th</sup> June, 2011



Close-up: Spill due to corrosion between 6 and 7 o'clock position on 24" Nkpoku-Boma pipeline at Akpajo. Picture taken during Joint Investigation of 17<sup>th</sup> June, 2011