



Overview: Impacted area within Obigbo Well20T wellhead facility at Umuebule. Picture taken during Joint Investigation of 28th June, 2011



Close-up: Spill due to corrosion on Obigbo Well20T flowline at Umuebule. Picture taken during Joint Investigation of 28th June, 2011