



Overview: Spill impact on surrounding vegetation on 12" Imo River1 to Oghale pipeline Right of Way at Owaza. Picture taken during Joint Investigation of 15<sup>th</sup> June, 2011



Close-up: Spill due to illegally welded nipple at 2 o'clock position on 12" Imo River1 to Oghale pipeline at Owaza. Picture taken during Joint Investigation of 15<sup>th</sup> June, 2011