



Overview: Part of the spill impact on Imo River Well 55S flowline at Igiriukwu. Picture taken during Joint Investigation of 17<sup>th</sup> June, 2011



Close-up: Hacksaw cut on Imo River Well 55S flowline at Igiriukwu. Picture taken during Joint Investigation of 17<sup>th</sup> June, 2011