




Overview: Part of spill impact on 16" Bonny Disused Export Pipelines at Bonny. Picture was taken during Joint Investigation of 2nd August 2018.



Close-up: Crude oil seeping from ground on 16" Bonny Disused Export Pipelines at Bonny. Picture was taken during Joint Investigation of 2nd August 2018.



Close-up: Corroded Disused 16" Flanges on 16" Bonny Disused Export Pipelines at Bonny.
Picture was taken during Joint Investigation of 2nd August 2018.