




Overview: Part of spill impact on 12" Imo River - Ogale Pipeline at Umuololo . Picture was taken during Joint Investigation 9th June 2020.



Close-up: 2" Crude oil theft valve on a locally fabricated clamp on 12" Imo River - Ogale Pipeline at Umuololo . Picture was taken during Joint Investigation 9th June 2020.