



Overview: Extent of the spill incident impact on Opukushi W-34T flowline ROW. Pictures taken during Joint Investigation of 18th March, 2011



Close-up: Spill due to corrosion on Opukushi W-34T flowline ROW.. Picture taken during Joint Investigation of 18th March, 2011.