



Overview: Extent of the spill incident impact on Otumara W-44S Wellhead riser. Pictures taken during Joint Investigation of 28th March, 2011



Close-up: Spill due to corrosion on Otumara W-44S Wellhead riser .Picture taken during Joint Investigation of 28th March, 2011.