



Overview: Part of spill impact on Agbada 2 Well66L flowline right of way at Umuokwa. Picture was taken during Joint Investigation of 19<sup>th</sup> March 2013.



Close up: Leak due to corrosion on Agbada 2 Well66L flowline at Umuokwa. Picture was taken during Joint Investigation of 20<sup>th</sup> March 2013.