



Overview: Part of spill impact on Imo River1 Well13L gaslift line right of way at Igirukwu/Isi-Etithoha. Picture was taken during Joint Investigation of 12<sup>th</sup> March 2013.



Close up: Drilled hole on Imo River1 Well13L gaslift line at Igirukwu/Isi-Etithoha. Picture was taken during Joint Investigation of 13<sup>th</sup> March 2013.