



Overview: Part of spill impact on Opukushi Well34T flowline right of way at Egbemo-Angalabiri. Picture was taken during Joint Investigation of 2<sup>nd</sup> April 2013.



Close up: Raised pipe on Opukushi Well34T flowline at Egbemo-Angalabiri. Picture was taken during Joint Investigation of 4<sup>th</sup> April 2013.



Close up: Leak due to corrosion on Opukushi Well34T flowline at Egbemo-Angalabiri. Picture was taken during Joint Investigation of 4<sup>th</sup> April 2013.