



Overview: Part of spill impact on Well20T 6" flowline right of way at Otusega. Picture was taken during Joint Investigation of 17th May 2013.



Close up: Cut section of Well20T 6" flowline at Otusega. Picture was taken during Joint Investigation of 17th May 2013.