


**Overview:** Part of spill impact on 6" Imo River Well 59T Flowline at Igiriukwu\_Owaza. Picture was taken during Joint Investigation of 11<sup>th</sup> May 2018.



**Close-up:** Illegal fitting partly concealed in cast concrete on 6" Imo River Well 59T Flowline at Igiriukwu\_Owaza. Picture was taken during Joint Investigation of 11<sup>th</sup> May 2018.