



Overview: Part of spill impact on Cawthorne Channel3 Well4LS Flowline Right of Way at Sand Sand. Picture was taken during Joint Investigation of 14th November 2014.



Close-up: Spill due to corrosion on Cawthorne Channel3 Well4LS Flowline at Sand Sand. Picture was taken during Joint Investigation of 14th November 2014.