



Close-up: Spill due to corrosion on Obigbo AGG Process Drain Vessel 2" Drainline at Umuebulu. Picture was taken during Joint Investigation of 14<sup>th</sup> November 2014.