



Close-up: Hacksaw cut on Kolo Creek Well3T Flowline at Otuasega. Picture was taken during Joint Investigation of 12th November 2014.