




Overview: Spill point on Alakiri Well31L Wellhead at Ofiomina-Ama. Picture was taken during Joint Investigation of 24<sup>th</sup> November 2014.



Close-up: Position of missing Surface Safety Valve actuator on Alakiri Well31L Wellhead at Ofiomina-Ama. Picture was taken during Joint Investigation of 24<sup>th</sup> November 2014.



Close-up: Connection points to missing Cameron Control Unit on Alakiri Well31L Wellhead at Ofiomina-Ama. Picture was taken during Joint Investigation of 24<sup>th</sup> November 2014.