



Overview: Spill location on Ekulama 2 Well24T Flowline Right of Way at Freetown. Picture was taken during Joint Investigation of 5<sup>th</sup> December 2014.



Close-up: Failed weld on Ekulama 2 Well24T Flowline at Freetown. Picture was taken during Joint Investigation of 5<sup>th</sup> December 2014.