



Overview: Part of spill impact on 4" Adibawa Well 12T Flowline at Edagberi. Picture was taken during Joint Investigation of 30<sup>th</sup> November 2018.



Close-up: Hacksaw Cut on 4" Adibawa Well 12T Flowline at Edagberi. Picture was taken during Joint Investigation of 30<sup>th</sup> November 2018