



Overview: Part of spill impact on 14inch Okordia Rumuekpe Trunkline at Edeoha. Picture was taken during Joint Investigation on 19th November 2020.



Close-up: Plugged 2inch Ball valve installed at 12 o'clock position on 14inch Okordia Rumuekpe Trunkline at Edeoha. Picture was taken during Joint Investigation on 19th November 2020.