




Overview: Part of spill impact on Soku Well 14L at Soku. Picture was taken during Joint Investigation on 9<sup>th</sup> November 2020.



Close-up: Partially closed kerotex valve on Soku Well 14L at Soku. Picture was taken during Joint Investigation on 9<sup>th</sup> November 2020.