



Overview: Location of suspected bunkering point on 12" Egbema-Oguta pipeline right of way at Eziosu. Picture taken during Joint Investigation of 13th October, 2011.



Close-up: Illegal fitting discovered after excavation on 12" Egbema-Oguta pipeline at Eziosu. Picture taken during Joint Investigation of 13th October, 2011.