



**Overview:** Part of spill impact on Imo River1–Well 37 Flowline at Igiriukwu-Owaza. Picture was taken during Joint Investigation of 26<sup>th</sup> October 2018.



**Close up:** Illegal fitting on Imo River1–Well 37 Flowline at Igiriukwu-Owaza. Picture was taken during Joint Investigation of 26<sup>th</sup> October 2018.