



Overview: Part of spill point 1 impact on 20" Otumara Escravos Pipeline at Ajudaibo. Picture was taken during Joint Investigation of 6th October 2013.



Close up: Spill point 1 due to illegal fitting 20" Otumara Escravos Pipeline at Ajudaibo. Picture was taken during Joint Investigation of 6th October 2013..



Overview: Part of spill point 1 impact on 20" Otumara Escravos Pipeline at Ajudaibo. Picture was taken during Joint Investigation of 6th October 2013.



Close up: Spill point 2 - due to illegal fitting 20" Otumara Escravos Pipeline at Ajudaibo. Picture was taken during Joint Investigation of 6th October 2013.