



Overview: Part of spill impact on 8" Nkali - Imo River2 Delivery line at Muanyimochi-Odagwa. Picture was taken during Joint Investigation on 19th September 2020.



Close-up: Crude oil theft point installed at 9 o'clock position on 8" Nkali - Imo River2 Delivery line at Muanyimochi-Odagwa. Picture was taken during Joint Investigation on 19th September 2020.