Overview: Part of spill impact on 20inch Kolocreek Rumuekpe Trunkline at Odau. Picture was taken during Joint Investigation of 18th July 2021.

Close-up: 3inch valve installed at 12 o'clock position on 20inch Kolocreek Rumuekpe Trunkline at Odau. Picture was taken during Joint Investigation of 18th July 2021.