THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED 831677 0287 JOINT INVESTIGATION REPORT FOR INCIDENT NO: (Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties) A. GENERAL INFORMATION: 2. Type of incident * OIL AND GAS SPILL 1. Spill incident Number: WELL 5 RIVER 3 3. Name of Location Mo 4. Name of nearest community IGRUKWU . 5. State: ABIA 7. Type of Production facility/Installation FLOWLINE 8. Asset owner/ District. **B. INCIDENT INFORMATION:** 9. Details of incident a. Date of incident: 24 TH JUNE, 2012 b. Start date/time of investigation: 26 TH JUNE c. Investigation End date: 20th June d. Description of spill point environment Firmed soil Loose soil ☐ Previously excavated area Under water Exposed pipe surface □ Swampy ☐ Well Plateform (on Water) \square_{Rig} e. Description of leak point (tick as applicable); □Drilled hole Hack saw cut ☐ Explosive tear, Complete Rupture ☐ Inward dent, ☐ Well head tampering ☐Failed Weld-on illegal hot tap valve, ☐ Missing Pipeline/Flowline) ☐Crude oil theft (illegal) bunkering) point, ☐ Third party tampering with Clamp Third party tampering with valve setting, ☐ Third party tampering with flange, □Corrosion ☐ Saver-pit over flow, ☐ Surge vessel overflow Outward dent Flare System/Bund wall failure □Valve Failure Com unit failure ☐ Cold vent Relief valve failure DOTHERS (specify) CLAMP FAILURE: f. Incident caused by: **☑**Operational ☐Third party interference □_{Mystery} g. Spill point coordinates MINNA MID-BET Measuring unit Northing: (m) Easting: (N

Page 1 of 9

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA JOINT INVESTIGATION REPORT FOR INCIDENT NO: C. RISK ASSESSMENT 10. Type of environment: Land ☐ Swamp ■ Water ☐ Seasonal swamp Type of environment to which oil has spread: Land ☐ Swamp ☐ Water ☐ River (identify) ii. Weather condition □ Raining Sunny 11. Distance from the nearest sensitive habitat ☐ Government reserved and designated protected area ☐ Drinking water source ,m] ☐ Built up area ,m]☐ Farmlands ,m]☐ Fish Farm/Pond ,m] ☐ Fishing net ☐ Others (specify). 12. Containment measures put in place; □ Booms □ Trench ☐ Dyke ☐ Others: 13. Any pictures or video coverage? 14. Was there any disruption to the investigation? If yes give brief description: D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL 15. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
	Macia	1 5	*	100	= MO
		121	H (N	TTKEA (I LIME.
	110190	N CL C	,,,,,	1 12 1	
	<u> </u>				

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED

JOINT INVESTIGATION REPORT FOR INCIDENT NO:

16. Crops/Economic Trees

S/N	Type of crops	Young		Medium	Matured	Quantity	Comments
	11-6	- 1					
	MAKE	- 100	[P/>A_	AT IM	120
	14010W	VVI	111 A	4 1/4	<u>~7 \</u>	<u> 91 171</u>	
				<u> </u>			

17. Fish/Nets/Ponds

S/N	Fish/Nets/Ponds	Description		Quantity/Size	Comments
			N OC		N/O. 67
	MONT K	H(+++7X)		/A th	MPACL
	 				

18. Others (Specify) i.e. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
	MONE	WITHIN	ARCA OF	MPACT

E. GRAPHIC DESCRIPTION OF LEAK POINT While detail report of the leak point should be contained in the Leak report, overview sketch of the site should be added as an appendix 1)

MO RIVER 3 MELL 5 FLOWLINE AT IGRUKWIN SETTICIAN VIEW.

OID CLAMPED SPILL

POINT INITER AN HACKSAN

CHT AS INITERL CAUSE

FAILED CLAMP LEAKING

AREQUIND THE TOP RIGHT

SIDE SEAL OF THE CLAMP

FLOWLINE

44

FLOWLINE

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA-LIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO: 531677

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

19. Impacted area boundary Coordinates (If more than 12 points, Attach as an appendix 2)

S/N	Northing (m)	Easting (m)
202	108840.59	524099.44
203	108840.59	524102.52
215	108837.53	\$24096.35
20%	108834 - 46	524696.35
207	108831.38	524096 . 34
208	108831 - 39	524 093 - 26
209	[08808·32	524090 · 17
210	1.08825-25	524093-25
211	208819 · 11	534087.08
2/2	18886 . 03	524093.23
213	108812-95	524096-80
24	108763-23	524092-74
245	168787 - 27	524092-00

G. INCIDENT INFORMATION:

20.	Impa	icted	Area	Detail	S

	ated area of impact	0-07Ha		
Impact outsi		NO		
21. Volume of oil recov	vered before completion	of JIV (V _{recJ}):		
	Recovered	oll V mix	NIL	barrels
	residual volume on sit me of pool of free phase of a) occupied by pool of free	il (on land or confined v	vater body).	

	-	EVELOPMENT COM	PANT UP	20 2 8 21677	,		
JOINT INVES		ORT FOR INCIDENT	NO: <u>U</u>	287 831677			
iii. Emulsification	factor:3	<u> </u>		•			
iv.	Volume of	pool of free phase oil. V_{pool}	91:	8.81	barrels		
b. Computation of	of volume of infilt	rated oil in the soil (V _{inf})					
i		vered by the oil:	/				
i	Area of the po	ool of free phase oil in tou	ch with soi	l: O'Olm			
ii	_	h (m) below ground surfa					
i		MEDIUM					
V		porosity of the soil)	2570				
i	v. Volume	of infiltrated oil. V _{ist}		9.44	barrels		
21. Computation	of volume of oil	on open water based o	n standard	coloration.			
_	f oil on open water						
ii.√ Table of ave	rage depth of oil o	n water based on coloration	**				
	Thickness	Percentage					
ı	(mm)	coverage		olume (m3)			
Barely Visible	0.00004		<u></u>				
Silvery	0.00008	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	-				
Slight Color		 1/10 					
Bright Color	0.0003	, , ,	, 	0.00			
Duli	0.001	A ()()	H CA				
Dark	0.002		- ,	- 320			
Blackoil	0.1	-					
Emulsion (30% Oil)			D0/ T -	tal Volume N.L	bbl		
· iii.	Percent Total	il on open water. V			barrels		
22. Calculation o	1 1 150	and 3 44,5 in 1387	<u> 1· . — </u>	NIL			
	-						
i. Oil type: BONN Y MEDIUM							
ii. E-Factor: 15 %							
iii.	iii. Volume of evaporated oil. V evap: 3-22 barrels						
		tor) for SPDC Crude oil Bonny Light Bo	nny	1			
Oil Type	Days on site		edium	_			

Evaporation Factors (E-Factor) for SPDC Crude oil							
Oil Type	Days on site	Bonny Light	Bonny Medium				
Period Since Oil Spill	< 1 day	10%	5%				
	1-7 days	25%	15%				
	> 7 days	40%	25%				

^{*}If area is not same as the total area of impact, please indicate in the overview sketch ** Spill Factor from USCG FOG (2000 Edition)

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED


JOINT INVESTIGATION REPORT FOR INCIDENT NO: 23. Gross Total Estimated Spilled Volume $V_{Est}(bbls) = V_{evan}(bbls) + V_{wat}(bbls) + V_{inf}(bbls) + V_{pool}(bbls) + V_{recJ}(bbls)$ $V_{Est}(bbls) =$ 21. 46 BARRELS 3.22 + NIL + 9.44 + 8.81 + NIL 24. Net Total Estimated Spilled Volume $V_{\text{Est}}(bbls) = V_{\text{evap}}(bbls) + 0.6*V_{\text{wat}}(bbls) + V_{\text{inf}}(bbls) + V_{\text{pool}}(bbls) + V_{\text{rec}}(bbls)$ BARREIS' *Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site *Conversion of m3 to barrels is Total volume VT (m3) x 6.29 *Emulsification factor for spill on water to consider is 60% of volume of oil. 25. GENERAL STATUS OF THE SITE A. Joint investigation of the incident site found that there is no residual impact after the initial response and therefore recommend that the site be closed out B. Investigation of the incident site showed that there is residual impact on site requiring further works **26 REPRESENTATIVES** $\frac{26}{06}$ 20]2 at incident site by joint This report was filled and signed on the investigation representatives from Host Community □ • Department of Petroleum Resources [DPR]: □ National Oil Spill Detection and Response Agency [NOSDRA]: □ State Ministry of Environment [SME]: □ • Nigeria Police Force [NPF]:□ Shell Petroleum Development Company [SPDC]: □

Tick as applicable

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0287 83 677

27. Appendix 1: Overview sketch of the site



THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1287 831677

21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

S/N	Northing (Lini)	Easting (m)
216	108762 - 32	524102.46
	•	. //
		/
	·	