JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1021274 JIV report S/N: 0093

(Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties)

A. GENERAL INFORMATION:	
I. Spill incident Number: 1021274 2.Type of	of incident* DIL SPILL
3. Name of Location CRUDE OIL FOUND AROUND E	ELEROU WELLS I AND 2 WELLHEADS
4. Name of nearest community DG BOLOMA 5. State: BAYE	ELSA 6. LGA YENAGOA
7. Type of Production facility/Installation NoT APA ICABLES. A	sset owner/District NoT APPLICABLE
B. INCIDENT INFORMATION:	
<u> </u>	Exposed pipe surface Drill Rig  Tear (
f. Incident caused by:  ☐ Third party interference (Sabotage☐; crude theft☐; Line thef ☐ Operational ☐ Others (including Mystery spills) ☐	_
g. Spill point coordinates  Measuring unit Northing:  Northing:	Easting: NOT APPLICABLE

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1021274 JIV report S/N: 093

Э.	RIS	K ASSESSM	ENT							
	1	.0. Тур	e of environmen	t:		-				
		ZLand CMARSHY)	□Swamp	□Water	□se	asonal swa	mp□Shor	reline/Wat	erfront	
		i. Type	of environment	to which oil ha	s spread:					
		Land	Swamp	Water LCRE	EK) □R	iver (identif	y)			
		ii. Weat	ther condition							
	11.	□Rain Distance from	Sunny the nearest sens	□Dry itive habitat	□Wet	□Win	dy	□Hot	□cool	
			-	designated pro	tected area	[ [ ; [	,m] ,m] ,m] ,m]			
•		<ul><li>□ Fish Farn</li><li>□ Fishing n</li></ul>	n/Pond ·	TREES		[	,m] ,m]	PACTER	s by spill	
	12.		measures put in p	•			•		·	
		□Booms □Others:	□Trench	□Dyke	<b>Z</b> N	atural depre	ession	□Pit		
	13.	. –	or video coverag	e?		ſΧ	[ N ]			
	14.	Was there any	y disruption to th	e investigation?		[ Y] <b>/</b>	[ N ]			
f y	es gi	ive brief descrip	ption: INVESTIGA	TION_VIST	T OF I	2.Th A	गुरुगट्टा	2013	Was	
30	NC	lude on	AS THE CA	hae of	Spirit	DETERM	NIMATICI	N. DUR	THE DAIS	
		•	OF ISTH #	•			•		•	ELA EKKOK
D.	TYI	PE/NUMBERS	S OF PROPERT	ries, if any,	FOUND WI	тніх тні	E AREA C	)F SPREA	AD OF OIL	
	15.	Structures / ]	Properties							
S/N	7	Type of Struc	etures Des	cription Size	N	umber		Commo	ents	_
_	<del> </del>				<u>.</u>				<b></b>	_
	V	ONIE	\\\-\-	1124	ADER	וח	=  ^	APAC	<b>T</b>	

UU G 3

1	i6. Crops/Econor	nic Trees				
	<u> </u>					
S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
1.	PALM TREE				2 No.	WITHIN
				j		SPILL-
2.	SHRUBS	>			5 NO.	IMPACTE
						RETHIN

#### 17. Fish/Nets/Ponds

	N/S	Fish/Nets/Ponds	Description	Quantity/Size	Comments
L					
L		<b>\</b>			
	N	~	۸		
	$\mathbf{V}$	アンファ		1 N	
			er ilina M	ET U	11.07.01
			1		

18. Others (Specify) i.e. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
$\Box$	~··	Λ.	n	
$\Box$	$DN \vdash V$	<u> VII HIN #H</u>	K事士 り	= IMPACT
	) -	CC ] ((() / 1)	Q1 O1	1. 011-61

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1)

NOT APPLICABLE

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1021274 JIV report S/N:

## F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION 19. Impacted area boundary Coordinates (If more, Print and attach as an appendix)

S/N	Northing	Easting
		N 1
		1/7
		7
		MOM D
-		
_		
	<del>                                     </del>	<del>*</del>
	<u> </u>	¥` <u></u>
		M. T.
		20
	(1)	<del>V</del>
		<del>()`</del>
	- X	
	+ C Ma	
		-
	· · · · · · · · · · · · · · · · · · ·	-
	-	<u> </u>

#### **APPENDIX A**

JIV\_QGBOLOMA\_1021274

IMPACTED	AREA COORDINATES	[MINNA	MID-BELT)
INTERVIEW	WEW COOKDINATES	Mr. Inc. on a hit	

	S UNITU COOM	MINATES .	•
Name		_	
		(HEAVY IMPACT)	
wp519	113778.01	432537.05	
wp520		432530.93	
wp521	113774.9	432546.29	
wp522	113780.94	432580.21	
wp523	113777.84	432586.36	
wp524	113783.97	432592.54	
wp525	113759.32	432610.95	
wp526	113756.27	432604.78	
wp527	113737.77	432623.21	
wp528	113707.14	432592.29	
wp529		432570.8	
wp530	113741.06	432558.5	
wp531	113762.61	432546.25	
wp532	113756.48	432540.06	
wp533	113768.82	432527.77	
wp534	113768.81	432530.86	
wp535	113787.26	432527.84	
wp536	113778.07	432518.56	
wp537	113808.85	432503.25	
wp538	113818.09	432497.12	
wp539	113827.34	432487.9	
wp540	113821.2	432484.8	
wp541	113793.64	432456.97	
wp542	113787.49	432456.95	
wp543	113778.2	432478.5	
wp544	113747.38	432506.13	
wp548	113738.71	432511.48	
wp549	113745.18	432502.04	
wp550	113775.51	432476.93	
wp551	113786.2	432453.81	
wp552	113794.4	432454.3	
wp553	113821.5	432482.89	
wp554	113828.46	432485.38	
wp545	113836.57	432484.85	
wp546	113824.25	432494.06	
wp547	113809.07	432505.02	
wp555	113781.97	432518.45	
wp556	113789.43	432527.89	

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1021274 กก93 JIV report S/N: G. INCIDENT INFORMATION: 20. Impacted Area Details Total calculated area of impact Impact within SPDC R.O.W. Impact outside SPDC R.O.W 21. Volume of oil recovered before completion of JIV (Vrect): Recovered oil V<sub>recl</sub>: Barrels NIL 22. Computation of estimated residual volume on site a. Computation of estimated volume of pool of free phase oil (on land or confined water body). i. Area (m<sup>2</sup>) occupied by pool of free phase oil 4.030 Average Depth (m) of pool of free phase oil iii. Emulsification factor: iv. Estimated Volume of pool of free phase oil. Vpool: barrels b. Computation of estimated volume of infiltrated oil in the soil (V<sub>inf</sub>). 1. Estimated Volume of infiltrated oil at spill point (Vinf a) i. Area\* (m<sup>2</sup>) of soil covered by the oil: íi. leaking facility i.e  $P_{\rm c}$  (effective porosity of the soil Soil type: iii. vi. Oil type: BONNY LIGHT Cause of spill: V. Oil Residence time on site, day: 6 DAYS vii. Average depth of infiltration below leaking facility i.e. pipeline/flowline viii. ix. Estimated depth of infiltration around spill point: Estimated Volume of infiltrated oil at spill point. Viot a: barrels 2. Estimated Volume of infiltrated oil at second spill point [if applicable] (Vinf b) i. Area\* (m<sup>2</sup>) of soil covered by the oil: \_\_\_ ji. Average Depth (m) above leaking facility i.e. pipeline/flowline: iii. Soil type: P<sub>e</sub> (effective porosity ٧. Cause of spill: vii. Oil Residence time on site, day: viii. Average depth of infiltration below leaking facility i.e. pipeline/flowline:\_ Estimated depth of infiltration around spill point: ix.

3. Estimated Volume of infiltrated oil outside immediate spill point(s) region (Vinf c)

barrels

Estimated Volume of infiltrated oil at spill point. Vinf h:

i.	Area (m2) of soil	covered by the oil:		05		_
ii.	Area (m²) of the p	oool of free phase oil	in touch with	soil:	11	
iti.	Average Depth (n	n) below ground sur	face of infiltra	tion of oil:	0.002	
	Soil type:	_				•
	•••	osity of the soil)	Q-1			
			O IO			<del></del>
,	vi. Estima	ted Volume of infilt	rated oil. At	V <sub>inf</sub> :	0.09	barrels
•		olume of oil on op	en water base	ed on standard	l coloration.	
ii. <u>Table of a</u>	verage depth of o	il on water based or	coloration (	**Spill Facto Edition)	ors from USCG	FOG (2000
	Thickness (mm)	Percentage coverage	Volume (m.	3)		
Barely Visible		LUTTE MAN	, oranie (III	·,		
Silvery	0.00008		• •	7		
Slight Color	0.00015	No				
Bright Color	0.0003	140	A			
Dull	0.001	1 1	AKLE			
Dark	0.002	APPLA				
Black oil	0.1	14.				
Emulsion (30% Oil)						
,	Percent Total	100%				
iű.	Estimated Volu	ime of oil on open w	rater. V <sub>wat</sub> :	NIL.	Ba	arrels
24. Calculation	of evaporated vo	olume:			<u> </u>	
					000 -	C 0400
i. Estin	mated Volume a	vailable for evapo	ration withir	i surface area:	<u> </u>	P DILKE
ii. E-Fa	actor: 25%	<u> </u>				
iii.	EstimatedV	olume of evaporated	l oil. V <sub>evap</sub> :	96.35	Ba	arrels
		(E Fantan) for CD	DC Cm.da -:	<u>,</u>	<del></del>	
Evaj Dil Type	Days on site	(E-Factor) for SPI Bonny Light	Bonny M			
Dil Residence time	< 1 day	10%	Domiy M	5%		
7.1 TOSIGORO HIRO	1-7 days	25%		15%		

	4070	2570	
25. Net Estimated Spilled Volun			
$(bbls) + V_{recl}(bbls) = 46.3$	5+ NL+	0.09+ 288.°	18 + NIL
<del></del>			385.42
Estimated Reported Volume** V <sub>rep</sub> (bbls)	E 386 BP	IRRELS.	

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1021274 JIV report S/N: 0093

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of  $m^3$  to barrels is Volume (m3) x 6.29; \*\*Round up estimated volume to next whole number using the following rules:

	wing rules:		to next whole number t
•	Any spill volume in excess of - 1 bbl	is rounded up to the next whole number.	

Any spill volume in less than 1 bbt is rounded up to the next 0.1 bbt.

Examples: Calculated volume = 15.3 bbl ------ Reported volume = 16 bbl Calculated volume = 0.35 bbl ------ Reported volume = 0.4 bbl Calculated volume = 0.01 bbl ------ Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the IIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and quach to the IIV report.

#### 26. GENERAL STATUS OF THE SITE

	A.	Joint investigation of the incident site found that there is no residual impact after the initial
		response and therefore recommend that the site be closed out
_		
	В.	Investigation of the incident site showed that there is residual impact on site requiring further works

#### 27. REPRESENTATIVES

This report was filled, agreed and signed on the 15/pg/2013 by joint investigation representatives from

- Host Community: 5
- Department of Petroleum Resources [DPR]: D
- State Ministry of Environment [SME]:
- Nigeria Police Force [NPF]: 🗘
- Shell Petroleum Development Company [SPDC]:
- Signatories agree with reported findings:
- Separate DPR form has been filled out with same findings

Tick as applicable

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1021274 JIV report S/N: 0093

28. Appendix 1: Overview sketch of the site

