JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1023885 JIV report S/N: 0131

(Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties)

7. Type of Production facility/Installation OL FLOW LINES. Asset owner/District LAND 2.  B. INCIDENT INFORMATION:	A. GENERAL INFORMATION:	
4. Name of nearest community BISEN 5. State: BAYELSA 6. LGA YENAGOA  7. Type of Production facility/Installation DL FLOW LINES. Asset owner/District LAND 2  B. INCIDENT INFORMATION:  9. Details of incident a. Date of incident: 3Th August, 2013 b. Start date/time of investigation: 28Th August, 2013 c. Investigation End date: 23Th August, Actual investigation duration, days: World 2) Day's d. Description of spill point environment 2013 Firmed soil   Loose soil   Recently excavated area   Under water   Swampy   Exposed pipe surface   Drill Rig    c. Description of leak point (tick as applicable);   Drilled hole   Hack saw cut   Tear (	1. Spill incident Number: 1023885 2.Type o	f incident* OIL SPILL
B. INCIDENT INFORMATION:  9. Details of incident:  a. Date of incident:  b. Start date/time of investigation:  c. Investigation End date:  primed soil    Loose soil   Recently excavated area	3. Name of Location 4" ADIBAWA NORTH - E	AST (ADNE) FLOW LINE
B. INCIDENT INFORMATION:  9. Details of incident:  a. Date of incident:  b. Start date/time of investigation:  c. Investigation End date:  primed soil    Loose soil   Recently excavated area	4. Name of nearest community <b>BISENI</b> 5. State: <b>BAYI</b>	ELSA 6. LGA YENAGOA
9. Details of incident a. Date of incident: 3TH AUGUST, 2013 b. Start date/time of investigation: 28 TH AUGUST c. Investigation End date: 27TH AHBHST Actual investigation duration, days: Wo(2) bAYS d. Description of spill point environment 2013 Firmed soil   Loose soil   Recently excavated area     Under water   Swampy   Recently excavated area     Investigation durated area   Recently excavated area     Investigation duration, days:   Well head tampering excavated area     Investigation durated   Relief Clamp   Missing Pipeline/Flowline     Third party tampering with Clamp   Third party tampering with Clamp     Third party tampering with flange,   Surge vessel overflow,   Surge vessel overflow,     Bulging Outward   Flare System/Bund wall failure   Accidental 3rd party equipment impact   Valve Failure   Com unit failure   Accidental 3rd party damage     Third party interference (Sabotage of crude theft   Line theft   Accidental 3rd party damage     Operational   Others (including Mystery spills)	7. Type of Production facility/Installation <b>OL FLOW LINE</b> 8. As	sset owner/District LAND 2
a. Date of incident: 37H AUGUST, 2013 b. Start date/time of investigation: 28TH AUGUST Actual investigation duration, days: Two (2) bays d. Description of spill point environment 2013    Firmed soil	B. INCIDENT INFORMATION:	
Third party interference (Sabotage 7, crude theft □; Line theft □; Accidental 3 <sup>rd</sup> party damage □)  □ Operational □ Others (including Mystery spills)  g. Spill point coordinates    Measuring unit   Northing:   Easting:	a. Date of incident: 3TH AUGUST, 2013 b. Start date/time of investigation: 28 TH AUGUST c. Investigation End date: 27TH AUGUST Actual invest d. Description of spill point environment 2013  Firmed soil	Recently excavated area  Exposed pipe surface Drill Rig  Tear (
g. Spill point coordinates  Measuring unit  Northing:  MINNA MID-BELT  Easting:	Third party interference (Sabotage ; crude theft□; Line thef	
	g. Spill point coordinates  Measuring unit  Northing:	-BELT)

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1023885 JIV report S/N: 0131

C.

RIS	K ASSESSN	MENT							
10	). Ty	pe of environ	ment:		:				
	Land	□Swan	np 🗆 V	Vater	Seasonal	swamp□Si	horeline/Wat	erfront	
	і. Тур	e of environm			l:				
	Land	Swan	A SO NAL DV	Vater	□River (ide	entify)			
	ii. We	ather conditio	n						
11.	Rain Distance from	Sunny m the nearest		-	Vet 🔲	Windy	□Hot	□cool	
	□ Drinkin □ Built up □ Farmlar □ Fish Far □ Fishing	nds rm/Pond		d protected a	rea [ [ [ . [ [	,m, ,m] ,m] ,m] ,m]			
12.	Containmen	t measures pu	t in place;						
	Booms Others:	•	ch 🗆 r	Dyke	□Natural d	lepression	□Pit		
13.	Any pictures	s or video cov	erage?		[ Y	<b>V</b> [N]			
14.	Was there a	ny disruption	to the investig	ation?	[ <b>Y</b>	<b>√</b> [N]			
yes gi ITr MM	ve brief desc AL JIV UNITY	ription: ATTEMP MEMBER	T DN TH S FROM		OF AW KRAMA THERES	GUST 2 4 (E)	LOIS VAA AGBERI YING TI	S FRISTRI COMMUNI	TED B
É,	TIGATION	1 TEAM	ACCESS	TOT	E BIS	371 579	प्राप्त अत	5 THROU	GH THE
у, с	COMIT	CMMUNI RACTOR RS OF PROP	WHO	HAD F	MALOYE	D (H	EW.	ARREDR. AD OF OIL	אף אמים ב
15.	Structures	/ Properties							
N 7	Type of Stru	uctures	Description	Size	Number		Comm	ents	3
		,		_	-				
	ONF	-W	THIN	<b>-</b>	REA-	OF	MPA	eT -	

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1023885 JIV report S/N: 0131

16.	Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
	4.					
	NONE	WITHIN	ARI	A OF	<b>IMPAC</b>	

#### 17. Fish/Nets/Ponds


S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments	
1	IONE	WITHN	AREA D	F IMACT	

18. Others (Specify) i.e. Animal Traps

MANIFOLD.

S/N	Others	Description	Quantity/Size	Comments
<b> </b>	JONE W	THIN ARE	A OF	IMPACT
				<u> </u>

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1)



Page 3 of 9

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1023885 JIV report S/N:

0131

## F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

<ol><li>19. Impacted area</li></ol>	boundary	Coordinates (	lf more, Print	t and attach as an appendix)

	(MINNA MID-BE	LT )
S/N	Northing	Easting
WP849	139253.46mN	451423·32mE
	139256.54mN	451423 · 33mE
	139259-61mN	451423.34mE
	139274.99mN	451417 · 23mE
	139250.38mN	451426 - 39ME
	139269.93mN	451408.47ME
1 - 1	139255 · 24mN	451410.05mE
	139260.24mN	451404 · 10mE
WP874	139249.21mN	451411.56ME
wP875	139247.46mN	451420.21mE
<del></del>		

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1023885 JIV report S/N: 0131

G. INCIDE	ENT INFO	DRMATION:	
20. Im	pacted A	area Details	
	<b></b>	al calculated area of impact 0.035 Ha	
		<u> </u>	
	•	pact within SPDC R.O.W YES	-
	-	pact outside SPDC R.O.W NIL	
21. <u>V</u>	olume of	oil recovered before completion of JIV (V <sub>recJ</sub> ):	Barrels
	Į	Recovered oil V <sub>recJ</sub> .	Barreis
22. <u>Cc</u>	mputatio	on of estimated residual volume on site	
a. Co		n of estimated volume of pool of free phase oil (on land or confined water bod Area (m²) occupied by pool of free phase oil	y).
	ii.	Average Depth (m) of pool of free phase oil 0 • 025	
	iii.	Emulsification factor: N1L	
	iv.	Estimated Volume of pool of free phase oil. V <sub>pool</sub> : 51-11	harrels
~		n of estimated volume of infiltrated oil in the soil (V <sub>inf</sub> ).  mated Volume of infiltrated oil at spill point (Vinf a)  Area* (m²) of soil covered by the oil:  Average Depth (m) above leaking facility i.e. pipeline/flowline:  Soil type:  Cause of spill:  Oil type:  Bonny  Medium  Oil Residence time on site, day:  Average depth of infiltration below leaking facility i.e. pipeline/flowline  Estimated depth of infiltration around spill point:  X.  Estimated Volume of infiltrated oil at spill point. V <sub>inf a</sub> :	PLICABLE
			barrels
	Z. Estu	mated Volume of infiltrated oil at second spill point [if applicable] (Vinf b)	
	i.	Area* (m²) of soil covered by the oil:	
	ii.	Average Depth (m) above leaking facility i.e. pipeline/flowline:	
	iii.	Soil type: iv. P <sub>c</sub> (effective porosity of the spil)	<del></del>
	٧.	Cause of spill: vi. Oil xpe:	
	vii.	Oil Residence time of site day:	
	viji.	Average depth of infiltration below leaking facility i.e. pipeline/flowline:	
	ix.	Estimated depth of infiltration around spill point:	_

3. Estimated Volume of infiltrated oil outside immediate spill point(s) region (Vinf c)

Estimated Volume of infiltrated oil at spill point. Vinf.,b:

barrels

i. A	Area (m2) of soil	covered by the oi	l:	25		
	_	pool of free phase			111	•
_	•	n) below ground s			•	_
	·	- <u>-</u>	unace of minital		JA OW TI	
	Soil type:	,	04			
<b>v</b> .		osity of the soil)				
v	/i. Estima	ated Volume of in	filtrated oil. At V	inf:	0.05	barrels
00.0	6 1	1 0 11			•	•
23. Computation				d on standai	d coloration.	
	of oil on open wa verage depth of o	ater: NII oil on water based				
<u>14010 01 41</u>	vorago depair or e	MI OII WAICH GRISCU	on coloration (	**Spill Fac Edition)	tors from USCG F	OG (2000
	Thickness	Percentage		•		
Dosely Winible	(nun)	coverage	Volume (m3)	) 		
Barely Visible	0.00004	11-	<u> </u>	$\dashv$		
Silvery Slight Color	0.00008	-No-1		-		
Bright Color	0.00013			-		
Dull	0.0003			$\dashv$		
Dark	0.002	Hepii	CARLE	1		
Black oil	0.1		SIVEL	1		
				1		
Emulsion (30% Oil)	[ ]			╛		
[	Percent Total	100%			l n	<del></del>
iii.		ime of oil on open	water. V <sub>wat</sub> :	NIL.	Bar	reis
24. Calculation o	of evaporated vo	olume:				
i. Estin	nated Volume a	wailable for eva	noration within	curface area	51 16 R	ADDE
	*	ivanable for eva	poration within	surrace area	. <u> </u>	TINKE
I. ESHI						
	ctor: <u>25%</u>					
ii. E-Fa		aluma of augustation	red ail W		n	
		olume of evaporat	ted oil. V <sub>evap</sub> :	17.05	, Bar	rels
ii. E-Fa	EstimatedVe			17.05	Bar	rels
ii. E-Fa	Estimated Vo	(E-Factor) for S	SPDC Crude oil		Ban	rels
ii. E-Fa	EstimatedVooration Factors Days on site			dium	Bar	rels
ii. E-Fa	Estimated Vo	(E-Factor) for S	PDC Crude oil Bonny Med		Bar	rels
ii. E-Fa	EstimatedVooration Factors Days on site < 1 day	(E-Factor) for S Bonny Light 10%	SPDC Crude oil Bonny Med	dium 5%	Bar	rels
ii. E-Fariii.  Evapo Oil Type Oil Residence time	Oration Factors Days on site < 1 day 1-7 days > 7 days	(E-Factor) for S Bonny Light 10% 25% 40%	SPDC Crude oil Bonny Med	dium 5% 15% 25%		
ii. E-Fa iii.  Evape Oil Type Oil Residence time	Estimated Volume  Oration Factors  Days on site  < 1 day  1-7 days  > 7 days  ed Spilled Volume	(E-Factor) for S    Bonny Light   10%   25%   40%	Bonny Med  Bonny Med  Vevap(bbls) +	dium 5% 15% 25%	+ V <sub>inf</sub> (bbls)	
ii. E-Fariii.  Evapo Oil Type Oil Residence time	Estimated Volume  Oration Factors  Days on site  < 1 day  1-7 days  > 7 days  ed Spilled Volume	(E-Factor) for S Bonny Light 10% 25% 40%	Bonny Med  Bonny Med  Vevap(bbls) +	dium 5% 15% 25%	+ V <sub>inf</sub> (bbls)	

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1023885 JIV report S/N: 0131

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of  $m^3$  to barrels is Volume (m3) x 6.29; \*\*Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of 1 bbl is rounded up to the next whole number.
- Any spill volume in less than I bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl ----- Reported volume = 16 bbl

Calculated volume = 0.35 bbl ------ Reported volume = 0.4 bbl Calculated volume = 0.01 bbl ------ Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plaid sheet of paper and attack to the JIV report.

#### 26. GENERAL STATUS OF THE SITE

- A. Joint investigation of the incident site found that there is no residual impact after the initial response and therefore recommend that the site be closed out
  - B. Investigation of the incident site showed that there is residual impact on site requiring further works

#### 27. REPRESENTATIVES

This report was filled, agreed and signed on the 29/08/2013 by joint investigation representatives from

- Host Community:
- Department of Petroleum Resources [DPR]: ☑
- National Oil Spill Detection and Response Agency [NOSDRA]:\*2
- State Ministry of Environment [SME]: □
- Nigeria Police Force [NPF]: □
- Shell Petroleum Development Company [SPDC]:
- Signatories agree with reported findings:
- Separate DPR form has been filled out with same findings

Tick as applicable

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1023885 JIV report S/N: 0131

28. Appendix 1: Overview sketch of the site

