JOINT INVESTIGATION REPORT FO	R INCIDENT NO: 1 666	157_JIV report S/N: 0337
(Note: As practicable as possible the	JIT report is to be signed in	the field by all the participating parties)
A. GENERAL INFORMATION:		
1. Spill incident Number: 2013.	- 1066157 2.Ty	ype of incident* OIL SPILI
3. Name of Location 14" OKOP	DIA-RUMUERPE	TIL AT IKARAMA
4. Name of nearest community	ARMM 5. State: R	AYELSA 6. LGA VENAGON
		8. Asset owner/District Kolo CREEL
B. INCIDENT INFORMATION:		
9. Details of incident a. Date of incident: 2 - NO: b. Start date/time of investigati c. Investigation End date: 6 - d. Description of spill point en	ion: <u>6 - Nov-2013</u> - Nov-2013 Actual is	nvestigation duration, days: 6 N E
Relief valve failure f. Incident caused by: Third party interference (Sab	Ek as applicable); Thack saw cut Inward dent, ap valve, Failed Clamp nkering) point, th valve setting, Saver-pit over flow Flare System/Bund Valve Failure Others (specify)	□ Exposed pipe surface □ Drill Rig □ Tear (), □ Well head tampering □ Missing Pipeline/Flowline □ Third party tampering with Clamp □ Third party tampering with flange, w, □ Surge vessel overflow, d wall failure □ Accidental 3 rd party □ com unit failure □ Cold vent theft□; Accidental 3 rd party damage□)
g. Spill point coordinates Measuring unit MET Northing:	37.92	14(MID-BELT) Rasting: 443645 07

JOINT IN	VESTIGATION F	REPORT FOR INCIDE	ENT NO: LO	66157	JIV repo	orts/N: U	1337
C. F	RISK ASSESSM	ENT					
	10. Type	e of environment:					
	Land	□Swamp □	Water	Seasonal swa	ımp□Sh	oreline/Wat	erfront
	і. Туре	of environment to which	ch oil has spread	!:			
	Land	Swamp]Water	River (identif	fy)		-
	ii. Weat	her condition					
:	☐Rain 11. Distance from	Sunny the nearest sensitive ha	Dry □w	/et □Win	ıdy	□Hot	□cool
	☐ Governme ☐ Drinking v ☐ Built up a: ☐ Farmlands ☐ Fish Farm ☐ Fishing ne ☐ Others (sp	rea s /Pond et	ated protected a	rea [,m] ,m] ,m] ,m] ,m]		
:	12. Containment n	neasures put in place;					
	Booms Others:	□Trench	Dyke	□Natural depre	ession	□Pit	
;	13. Any pictures o	r video coverage?		W	[N]		
:	14. Was there any	disruption to the invest	igation?	[Y]	W	•	
If yes	s give brief descrip	tion:					
_	Ma	TA	DD 1	A		1 P	
	1 40		176	1 6 /4	-15		
	YPE/NUMBERS	OF PROPERTIES, I	F ANY, FOUN	D WITHIN THI	E AREA	OF SPREA	D OF OIL
S/N	Type of Struct	ures Description	Size	Number		Comments	5
1		<u> </u>	 				
— R —	† 7	- 1	i -				

5/N	Type of Structures	Description	Size	Number	Comments
1		· · · · · ·			
	,_				- :-
		A 15	_	N V DV V	JM DV OC
\Box		$\Pi \Pi \Lambda \perp$		11-12 F-11- UT	
		 	1/7	4 1 1 2 Cart - 21	*
	•	1			
$\overline{}$	C C/Ei- T		•	<u> </u>	·

16. Crops/Economic Trees

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1066157 JIV report S/N:

0337

S/N Type of crops	Young	Medium	Matured	Quantity	Comments
2 PALMITERES			`\ 	141277	
2 PALMITURES		<u> </u>		E1 5 # T	
3 PLANTAINTU	Set			THREE	

17. Fish/Nets/Ponds


S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
\perp	निडम	SCALLED.	ONE (SMAU)	
L				
 - /-				
/ 	 			
\vdash			/	
<u>K</u>			<u> </u>	

18. Others (Specify) i.e. Animal Traps

S/N Others	Description	Quantity/Size	Comments
NONE	WITHIN	AREA OF	LMPACT

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1)

SECTION OF 14" OKOKAIA - RUM WEIGHE TRUNKLINE ATTIMAM SHOWING POSITION OF HAUCSAND CUT.



F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 156157 JIV report S/N: 0337

19. Impacted area boundary Coordinates (If more, Print and attach as an appendix)

	71000101	(MW-BELT)
S/N	Northing METERS	Easting METERS
	127847.15	443642.02
	127837.95	4 43 635 · 83
	127 831.80	443638.89
	127798.14	443592.59
	127785.94	443564.80
	127776:71	443 567 . 85
	127770 . 54	443577.07
	127767.43	443586 - 31
	127752 06	443 589 · 34
	127776.55	443617.14
	127782.65	443 632 . 57
	127770.31	443647.93
	127785.68	443644 · 90
	127797.87	443675.75
	127849 . 97	443722 . 14
	127771.86	443649.39
	127 783.52	443638.11
	127825.96	443698 33
	127864 · 88	443705.79
	127853.99	443679.60

G. INCIDENT INFORMATION:

20. Impacted Area Details

•	Total calculated area of impact_	<u>0:64 Ha</u>
•	Impact within SPDC R.O.W_	YES
•	Impact outside SPDC R.O.W	785

21. Volume of oil recovered before completion of JIV (V_{recJ}):

		Recovered oil V _{reci} :	<u> </u>	Barrels
		Recovered on V _{rec.j} :	<u> </u>	
22	. Computati	on of estimated residual volume on site		
a.	Computatio	n of estimated volume of pool of free phase oil (on land or		dy).
	i.	Area (m²) occupied by pool of free phase oil		-
	ii.	Average Depth (m) of pool of free phase oil	002	-
	iii.	Emulsification factor: O %		
	iv.	Estimated Volume of pool of free phase oil.	<i>a</i>	barrels
		V _{pool} :	80.51	
b.		n of estimated volume of infiltrated oil in the soil (V_{inf}) . nated Volume of infiltrated oil at spill point (Vinf a)		
	i.	Area* (m²) of soil covered by the oil:		
	ii.	Average Depth (m) above leaking facility i.e. pipeline/flo	wline: 1.50	
	iii.	Soil type: CLAY iv. Pe (effective porosity of		
	v.	Cause of spill.		
	vii.	Oil Residence time on site, day:	—— »· •••	•
	viii.	Average depth of infiltration below leaking facility i.e. pip	eline/flowline: 0	Oplim
	ix.		5011 m	·
		x		
		Estimated Volume of infiltrated oil at spill point Viet	3-02	barrels
	2. Estir	nated Volume of infiltrated oil at second spill point [if appl	icable] (Vinf b)	-
	i.	Area* (m²) of soil covered by the oil:	10	
	ii.	Average Depth (m) above leaking facility i.e. pipelire/fl	W -	
	iii.	Soil type:	the soil)	
	v.	Cause of spill:		
	vii.	Oil Residence time on tite, day		
	viii.	A crare depth of infiltration below leaking facility i.e. pip	eline/flowline:	
	ix.	Estimated depth of infiltration around spill point:		_
	·	stimated Volume of infiltrated oil at spill point. Vara	MIL	barrels
	3. E			
		ated Volume of infiltrated oil outside immediate spill point(s) region (Vinf c)	
	i.	Area (m2) of soil covered by the oil: 896	201	
	ii.	Area (m ²) of the pool of free phase oil in touch with soil:_	896	
	iii.	Average Depth (m) below ground surface of infiltration of	oii: 0.002	
	iv.	Soil type:		
	v.	P _e (effective porosity of the soil).	-	
		vi. Estimated Volume of infiltrated oil. At Vinf.	482	barre

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1066157 JIV report S/N: 0337

II. Table of average depth of oil on water based on coloration (

**Spill Factors from USCG FOG (2000 Edition)

•	Thickness (mm)	Percentage coverage	Volume (m3)	,
Barely Visible	0.00004			
Silvery	0.00008			1 1. 5
Slight Color	0.00015	$\perp \sigma \perp$	$\frac{1}{1}$	1,1A121R
Bright Color	0.0003	MUL	HVV	Man Bull
Dull	0.001	1 -		
Dark	0.002	<u> </u>	<u>'</u>	
Black oil	0.1			_
Emulsion (30% Oil)	1	1009/		
iii.	Percent Total Estimated Volume	100% ume of oil on ope		Harrels Barrels
· · · · · · · · · · · · · · · · · · ·			,	<u> </u>

24. Calculation of evaporated volume:

i. Estimated Volume available for evaporation within surface area: 85.34 Bis

ii. E-Factor: 154.

iii. EstimatedVolume of evaporated oil. Vevap: 15.06

Barrels

Evaporation Factors (E-Factor) for SPDC Crude oil						
Oil Type Days on site Bonny Light Bonny Medium						
Oil Residence time	< 1 day	10%	5%			
	1-7 days	25%	15%			
> 7 days 40% 25%						

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of m^3 to barrels is Volume (m3) x 6.29; **Round up estimated volume to next whole number using the following rules:

Any spill volume in excess of 1 bbl is rounded up to the next whole number.

Any spill volume in less than | l bbl | is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl ----- Reported volume = 16 bbl Calculated volume = 0.35 bbl ----- Reported volume = 0.4 bbl Calculated volume = 0.01 bbl ----- Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

26. GENERAL STATUS OF THE SITE

A.	Joint investigation of the incident site found that there is	no residu	al impact after	the initial
	response and therefore recommend that the site be closed ou	ıt 📮		

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 106157 JIV report S/N: 0337

B. Investigation of the incident site showed that there is residual impact on site requiring further works


27. REPRESENTATIVES

This report was filled, agreed and signed on the <u>66/11/2012</u> by joint investigation representatives from

- Host Community:
- Department of Petroleum Resources [DPR]:
- National Oil Spill Detection and Response Agency [NOSDRA]:
- State Ministry of Environment [SME]:
- Nigeria Police Force [NPF]:
- Shell Petroleum Development Company [SPDC]:
- Signatories agree with reported findings:
- Separate DPR form has been filled out with same findings□

Tick as applicable

28. Appendix 1: Overview sketch of the site



JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1066157 JIV report S/N: 0337

