| IOINT INVESTIGATION REPORT FOR INCI | DENT NO: 10674 | 92 IIV report S/N: | 0070 |
|---|--|---|----------------------------|
| (Note: As practicable as possible the JIT rep | | | |
| A. GENERAL INFORMATION: | _ | y and participatin | g parnes) |
| 1. Spill incident Number: 1069492 | 2.Type | of incident* OIL SPIUL | • |
| 3. Name of Location 28 " Comy - | | LE MIGER PIPE | |
| 4. Name of nearest community B- bea | 5. State: RIVE | 22. 6. LGA Crock | nna. |
| 7. Type of Production facility/Installation | | | |
| B. INCIDENT INFORMATION: | | <u> III.</u> | 10 10 |
| 9. Details of incident a. Date of incident: 2 Th Notember b. Start date/time of investigation: 10 The Notember c. Investigation End date: 11 The Notember d. Description of spill point environme [Firmed soil] | R 2013 M November 2013 M See, 2613 Actual investint M Loose soil | stigation duration, days: <u>Tr</u> | |
| □ Well Platform (on Water) e. Description of leak point (tick as appoint) □ Drilled hole □ Complete Rupture □ Failed Weld-on illegal hot tap valve, □ Crude oil theft (illegal bunkering) □ Third party tampering with valve □ Corrosion | ☐ Hack saw cut ☐ Inward dent, ☐ Failed Clamp) point, setting, ☐ Saver-pit over flow, ☐ Flare System/Bund wa | Exposed pipe surface Drill Rig Tear (| with Clamp with flange, |
| Relief valve failure | Others (specify) | | |
| f. Incident caused by: Third party interference (Sabotage ; Operational Others (included) g. Spill point coordinates Measuring unit (M) Northing: | MINNA MU | 10; Accidental 3 rd party day 10 - 6e(7) 11ing: 1532 757. 4 | |
| | | • | |

| | THE SHELL | L PETROLEUN | N DEVELOP | MENT CO | MPANY OF N | IIGERIA L | IMTED. |
|------------|--|------------------------------|-------------------|-----------|---|------------------------|-----------|
| JOINT INVE | ESTIGATION F | REPORT FOR IN | ICIDENT NO | 10694 | <u>92</u> JIV re | port S/N: | 0272 |
| C. Ris | SK ASSESSMI | ENT | | | | | |
| | 10. Type | e of environment: | | | | | |
| | Land | □ Swamp | □water | □Sea | asonal swamp | Shoreline/W | aterfront |
| | i. Type | of environment to | which oil has | spread: | | | |
| | Land | □ Swamp | □Water | □Riv | ver (identify) | | |
| | ii. Weatl | her condition | | | | | |
| . 11. | Main Distance from | Sunny the nearest sensiti | Dry ve habitat | □wet | \square Windy | □Hot | □cool |
| | ☐ Governme ☐ Drinking v ☐ Built up ar ☐ Farmlands ☐ Fish Farm ☐ Fishing ne ☐ Others (spe | rea ; /Pond :t | esignated prote | cted area | [,m] [m,] [m,] [m,] [m,] | None Seen Vicini | MITHM |
| 12. | Containment m | neasures put in pla | ice; | | | | |
| | □Booms □Others: | □Trench | □Dyke | □Nat | arral depression | ₽it | |
| 13. | Any pictures or | r video coverage? | | | [Y] [N] | | |
| 14. | Was there any | disruption to the in | nvestigation? | | [Y] [N] | <u> </u> | |
| If yes gi | ive brief descript | tion: | | | | | |
| <u> </u> | No | | MPF |) [] (| (A) | JE. | |
| D. TYP | PE/NUMBERS | OF PROPERTIE | CS, IF ANY, F | OUND WIT | HIN THE ARE | A OF SPRE | AD OF OIL |
| | Structures / Pr | <u> </u> | | | | | |
| S/N T | ype of Structu | res Descrip | tion Size | Numi | er | Commen | ts |
| | | - | | | | | |
| | MC | KITH | HAL | 100 | 1x K | HMO | |
| 1 | 1011P | <u> </u> | 11/4 | UV | | 100 | |

16. Crops/Economic Trees

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1069492 JIV report S/N: 0272

| S/N | Type of crops | Young | Medium | 3.5.4 | | |
|-----|---------------|----------------|-------------------------------|----------------|-------------|---------------|
| V | CASSAUA | - | | Matured | Quantity | Comments |
| ~ | Pinappie | 2 | +- | | FEW | MULTINE AND |
| V | COCO YAM | - 7 | - - + <u>-</u> - - | <u> </u> | FIVE (S) | OUTSIDE SPOK |
| | (/41/ | | | 4 | TEN (10) | PICHET OF WAY |
| | | | | | | |
| | | | | + | | |
| | | | | <u> </u> | <u></u> | |

17. Fish/Nets/Ponds

| S/N Fish/Nets/Ponds Description | Quantity/Size Comments |
|---------------------------------|------------------------|
| MONE MITHIN A | REA OF IMPACT |

18. Others (Specify) i.e. Animal Traps

| S/N | Others | Description | Quantity/Size | Comments |
|-----|--------|-------------|---------------|----------|
| | PNE | LITHIN A | REA | a MPACT |

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1)

SECTIONAL VIEW OF 28' BOMU - BENNY TRANS NIGHT PIPELINE AT B-

DERE STOWNIG BUNKERING FITTING (FAILED)

LEAK FROM A 2" FAILED

BAH VALUE INSTALLED AT

12° CLOCK POSITION ON 28"

BOMU - BONNY TRANS NIGGE

PIPELIAE: AT B-DECE.

THE 28"

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

JOINT INVESTIGATION REPORT FOR INCIDENT NO: (069492 JIV report S/N: 0272

19. Impacted area boundary Coordinates (If more, Print and attach as an appendix)

| S/N I | Northing (M) | Easting (M) |
|-------|---------------------------------------|-------------|
| WP739 | 76 159.38 | 532 757.47 |
| 1740 | 76 162 - 46 | 532 754.39 |
| 19741 | 76 165 . 52 | 532 760.56 |
| 50742 | 76 165. 52 | 532 757.48 |
| w/743 | 76 165. 93 | 532 760.84 |
| N744 | 76156-29 | 532 766.71 |
| W1745 | 76 162. 45 | 532 760.56 |
| | | |
| | | |
| _ | | |
| - | | |
| | | |
| | · | |
| | . | |
| | | <u> </u> |
| | | / |
| - | | |
| | | |
| | | |
| | | |
| | | |
| | / | |
| / | · · · · · · · · · · · · · · · · · · · | |

G. INCIDENT INFORMATION:

20. Impacted Area Details

| • | Total calculated area of impact_ | 0.003 Ha. |
|---|----------------------------------|-----------|
| • | Impact within SPDC R.O.W | YES |
| • | Impact outside SPDC R.O.W | YES |

21. Volume of oil recovered before completion of JIV (V_{recl}):

| JOINT INVESTIGATIO | N REPORT FOR INCIDENT NO: 15694 | 92_ JIV re | eport S/N: 02 | 72 |
|--------------------|--|--|------------------|---------|
| | Recovered oil V _{recJ} : | NIL | Bar | rels |
| a. Computati | ion of estimated residual volume on site on of estimated volume of pool of free phase oil Area (m²) occupied by pool of free phase oil | (on land or confi | ned water body). | |
| ii. | 2 1 () k | 0,01 | m | |
| | Emulsification factor: 36% | _ | | |
| iv. | Estimated Volume of pool of free phase V_{pool} : | | 7.04 | barrels |
| _ | on of estimated volume of infiltrated oil in the so imated Volume of infiltrated oil at spill point (Vi | | | |
| i. | Area* (m²) of soil covered by the oil: | 2m2 | <u></u> | |
| ii. | Average Depth (m) above leaking facility i.e. 1 | pipeline/flowline | : <u> </u> | |
| iii. | Soil type: SiT iv. P_e (effective | | · | |
| v. | Cause of spill: THED PACTY vi. Oil type | : BENINY ME |) in | |
| vii. | Oil Residence time on site, day: Two Day | • | | |
| viii. | Average depth of infiltration below leaking fac- | cility i.e. pipeline | /flowline: 0 06 | 27m |
| ix. | Estimated depth of infiltration around spill poi | nt: 1. 203 | <u>7 m</u> | |
| | Estimated Volume of infiltrated oil at spil | l point. V _{inf_a} : | 2.65 | barrels |
| 2. Est | imated Volume of infiltrated oil at second spill p | oint [if applicabl | e] (Vinf b) | |
| i. | Area* (m²) of soil covered by the oil: | ML | | |
| ii. | Average Depth (m) above leaking facility i.e. 1 | pipeline/flowline | : <u>NIL</u> | |
| iii. | Soil type: NiL iv. P. (effective | porosity of the s | oil) | |
| v. | Cause of spill: vi. Oil type | NIL | _ | |
| vii. | Oil Residence time on site, day: | | | |
| viii. | Average depth of infiltration below leaking fac | cility i.e. pipeline | e/flowline: NIL | |
| ix. | Estimated depth of infiltration around spill poi | int: NIL | | |
| 3. E | Estimated Volume of infiltrated oil at spill poin | t. Ving b: NOT | APPLICARLE BATTO | els |
| stix | nated Volume of infiltrated oil outside immediate | e spill point(s) re | gion (Vinf c) | |
| i. | Area (m2) of soil covered by the oil: | 12 n | n ² | • |
| ii. | Area (m²) of the pool of free phase oil in touch | | | |
| iii. | Average Depth (m) below ground surface of it | nfiltration of oil: | 0.0027m |) |
| iv. | Soil type: StJT | | | |
| v. | Pe (effective porosity of the soil). 21 % | <u>. </u> | | |
| | vi. Estimated Volume of infiltrated oil | | 0.64 | barrels |

23. Computation of estimated volume of oil on open water based on standard coloration.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1069492 JIV report S/N: 1272

ii. Table of average depth of oil on water based on coloration (

**Spill Factors from USCG FOG (2000 Edition)

| | Thickness (mm) | Percentage coverage | Volume (m3) |
|--------------------|-------------------|------------------------|-------------|
| Barely Visible | 0.00004 | Maric | 0001 |
| Silvery | 0.00008 | NOVE | الم المحاد |
| Slight Color | 0.00015 | | |
| Bright Color | 0.0003 | MILH | 7 |
| Duil | 0.001 | | |
| Dark | 0.002 | VICIN | TY |
| Black oil | 0.1 | 11-4-1 | |
| Emulsion (30% Oil) | 1 | | |

iii. Estimated Volume of oil on open water. Vwat: NoT APLICABLE Barrels

24. Calculation of evaporated volume:

- i. Estimated Volume available for evaporation within surface area: 9.70 Brasels
- ii. E-Factor: 15%

iii. Estimated Volume of evaporated oil. V_{evap}: 1.72 Barrels

| Evaporation Factors (E-Factor) for SPDC Crude oil | | | | |
|---|----------|-----|-----|--|
| Oil Type Days on site Bonny Light Bonny Medium | | | | |
| Oil Residence time | < 1 day | 10% | 5% | |
| | 1-7 days | 25% | 15% | |
| | > 7 days | 40% | 25% | |

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of m^3 to barrels is Volume (m3) x 6.29; **Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of 1 bbl is rounded up to the next whole number.
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

26. GENERAL STATUS OF THE SITE

| A. | Joint investigation of the incident site found that there is no | residual | impact after | the initial |
|----|---|----------|--------------|-------------|
| | response and therefore recommend that the site be closed out | | | |

| JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1569492 JIV report S/N: | 0272 |
|---|------|
|---|------|

B. Investigation of the incident site showed that there is residual impact on site requiring further works

27. REPRESENTATIVES

This report was filled, agreed and signed on the N / N / 2013 by joint investigation representatives from

- Host Community:

 ✓
- Department of Petroleum Resources [DPR]:
- National Oil Spill Detection and Response Agency [NOSDRA]:
- State Ministry of Environment [SME]:
- Nigeria Police Force [NPF]:
- Shell Petroleum Development Company [SPDC]:
- Signatories agree with reported findings: <a>I
- Separate DPR form has been filled out with same findings□

Tick as applicable

28. Appendix 1: Overview sketch of the site

| Location 2 | Bonn | -BOHNT | TANNS | NICER | PIPELINE AT | B- bece |
|------------|------|--------|-------|-------|-------------|----------|
| | | | | | | <u>.</u> |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | • | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | • | ļ |

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1069492 JIV report S/N: 0272

