JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1298530 JIV report S/N: 00801 (Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties) A. GENERAL INFORMATION: 1. Spill incident Number: 1298530 2. Type of incident\* 012 SPILL 3. Name of Location 10" DIEBU CREHK - NUNRIVER PIPELINE 4. Name of nearest community Ekonie. 5. State: BATHSA6. LGA SOUTHERN TIAM! 7. Type of Production facility/Installation OIL PIPELINE 8. Asset owner/District PIPELINE **B. INCIDENT INFORMATION:** 9. Details of incident
a. Date of incident: 3RB DECEMBER, 2014 b. Start date/time of investigation: 10Th December, 2014/12:25pm. c. Investigation End date: DHO DECEMBER, 2 Actual investigation duration, days: ONE(1) DAY. d. Description of spill point environment Recently excavated area Loose soil Firmed soil Exposed pipe surface Swampy □Under water □Drill Rig ☐ Well Platform (on Water) Additional observations around the spill point: e. Description of leak point (tick as applicable); Hack saw cut Tear ( Drilled hole ☐Inward dent, ☐ Well head tampering Complete Rupture ☐Missing Pipeline/Flowline ☐Failed Weld-on illegal hot tap valve, ☐Failed Clamp Third party tampering with Clamp ☐Crude oil theft (illegal bunkering) point, ☐Third party tampering with flange, ☐ Third party tampering with valve setting, ☐Surge vessel overflow, ☐Saver-pit over flow, ☐ Corrosión ☐Flare System/Bund wall failure ☐Accidental 3rd party equipment ☐Bulging Outward Com unit failure Cold vent ☐ Valve Failure impact Others (specify) Relief valve failure f. Incident caused by: Third party interference (Sabotage , crude theft□; Line theft□; Accidental 3rd party damage□) Others (including Mystery spills)\_\_\_\_\_ Operational

<sup>\*</sup>This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire,

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 12985	530 JIV report S/N: 00801
g. Spill point coordinates:  Measuring unit (M)	Mid belt
Northing:	Easting:
79/19.55	402276.01
7 00	
	2001
C. RISK ASSESSMENT	
10. Type of environment:	
□Land ☑Swamp □Water □Se	easonal swamp Shoreline/Waterfront
<ol> <li>Type of environment to which oil has spread:</li> </ol>	
□Land □Swamp □Water □Ri	ver (identify)
ii. Weather condition	
Rain Sunny Dry Wet  11. Distance from the nearest sensitive habitat	□Windy □Hot □cool
Government reserved and designated protected area Drinking water source Built up area Farmlands Fish Farm/Pond Fishing net Others (specify).	[ ,m] [ ,m] [ ,m] [ ,m] ,m]
12. Containment measures put in place;	
Booms Trench Dyke ZNz  Others: LUCAL CUNTAMMENT	atural depression
13. Any pictures or video coverage?	[N]
14. Further response/repair initiated as at the time of IIV?	M [N]
1f yes to item 14, give brief description: RECOVERY AE	THES ON GOING.
REPAIR WAS DONE ON METERIFA	SECTION OF THE POPULING
REPAIR NIAS DONE ON AFFECTED  BY CLAMPING.  15. Was there any disruption to the investigation?	[Y] <b>W</b>
If yes to item 15 give brief description:	
NOT APPLICABLE.	<del>-</del>

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1298530 JIV report S/N: 00801

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

16. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
N	one wis	HIN	ARE	4 OF I	MART
	2 C-a-a/Easmannia T				

17. Crops/Economic Trees

S/N Type of crops	Young	Medium	Matured	Quantity	Comments
None	KITHIN	ARCI	7 OF	IMPI	107

18. Fish/Nets/Ponds

S/N	Fish/Nets/Ponds	Description		Quantity/Size	Comments
1	ONE W	17HIN	ARC.	4 OF	IMPACT

19. Others (Specify) i.e. Animal Traps

S/N Others	Description	Quantity/Size	Comments
MONE	HITHIN AR	GA OF	IMPACT

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1)

HOWING HACK SAW CUT AT 1-2 D'CLOUR POSITION.

FROM DIEBU CREEK TO MANY RIVER.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1298530 JIV report S/N: 00801

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION 20. Impacted area boundary Coordinates (If more Print and attact of ampipentix)

	. Impacted area boundary Cooldmates (1) me	
S/N	Northing (m)	Easting (M)
	78982.34	402270.30
	78982.34	402263.15
	79077.24	402266.41
	79083.38	402269.51
,	79110.54	402277.44
	79114-11	402269.62
	79132.55	402269.68
	79133 - 49	402278.06
	79147.91	402272.82
	79147.83	402280.31
		7
<u> </u>		/
	/	12
		56 61
		10/12/2014
		10/12/2014
	/	
	<del> </del>	
		<u> </u>

### **ESTIMATION OF OIL SPILL VOLUME**

		E/OFF\$HORE (Leak stopped a	t source)		
lmp	acted Area Details				
	Total Calculated Area of				1,000.00 m²
	Impact within SPDC R.O.			•	m²
Ì	i Impact outside SPDC R.C	).W			]m²
Volu	ıme of oli recovered befor	re completion of JIV (V <sub>rec.i</sub> )			
	Estimated Recovered oil (				bbls
	(m.41				
	Estimated Recovered oil	(Net) V <sub>ncJ</sub>			0.00 bbla
Con	putation of estimated res	idual volume on site			
a .		of free phase oil (on land or confined	i water body)		
i	Total area occupied by po				250.00 m²
	Average depth of pool of f				0.001 m
iii	Emulsification factor	(If applicable, else 0%)			0 %
	Estimated Volume of po	n) of free whose all M			
	Estimated Volume of po				0.25 m <sup>3</sup> 1.67 bbls
		344			1.or Mote
b		d volume of infiltrated oil in the soil	(V <sub>tot</sub> )		
	Volume of infiltrated oil a				
i	Total area covered by the	oil (infiltration)			1.00 m²
ii	Average depth of infiltration	n above leaking facility i.e. pipetine/flov	vline		1.200 m
	Soil type				Sifty or sandy clay
Ì¥	P. (effective porosity of the	e soil)			12 %
1/	Cause of spill				
•	Cause of spill				Third party interference
V	Calculation of days for	infiltration below the leaking point on p	ipeline or flowline		
	Incident Date	JIV Date	Days on Site		
	12/3/2014 9:45	12/10/2014 12:25	7		
		rational, use 1 week as worst case here 'days on site' exceeds 7.	7		
		I-MIL-MI			7
	Caittea	Infiltration of oil types in various soil t	<u> </u>	- : · · · ·	4
	Soil type	Approximate time to reach			4
	Oil type Bonny Medium	Sand	Loam	Clay	4
	Bonny Light	3 weeks 2 days	3 years 2 months	> 10 years	-
	Johny Light		2 1710110115	> 10 years	_
vii	Oil type				Bonny Light
VÜİ	Average depth of infiltration	n below leaking facility i.e. pipeline/flow	line		0.002 m
ίX	Total depth below ground :	surface of infiltration of oil			1.202 m
	Estimated Volume of Infl.	itrated oil. V			0.14 m³
	Estimated Volume of Infi				0.91 bbls
				-	v.o.i whis
		t second spill point [if applicable] (V	( <sub>kef b</sub> )		
	Total area covered by the	'			m²
		n above leaking facility i.e. pipeline/flow	/line		m
	Soil type				- Select -
įų	P <sub>e</sub> (effective porosity of the	: SON)			0 %
٧	Average depth of infiltration	n below leaking facility i.e. pipeline/flow	line		0.000m
γi	Total depth below ground s	uurface of infiltration of oil			
VI	, -				0.000 m
	Estimated Volume of Infil			_	0.00 m <sup>3</sup>
	Estimated Volume of Infil		0.00 bbis		

	utside immediate spili point(s) regic	on (V <sub>infe</sub> )							
Total Area covered by the o	· ·			1,949.00 m²					
Total Area of the pool of fre	50.00 m²								
Soil type	Sility or sandy clay ▼ 12 %								
V P. (effective porosity of the soil)									
Average depth below groun	0.002 m								
Estimated Volume of Infil	trated oil, V <sub>lafe</sub>			0.46 m <sup>3</sup>					
Estimated Volume of Infil	trated oil, V <sub>inf c</sub>			2.89 bbis					
Volume of infiltrated oil o	utside immediate spill point(s) regic	nn feunarfielet imnee	• W 3						
Total Area covered by the		on fanhameren mibec	S * kafd)	m²					
•	ee phase oil in touch with soil			m²					
·	·								
Average depth below grour	nd surface of infiltration of oil			0.002 m					
Estimated Volume of infil	funtariali V			0.00 m <sup>3</sup>					
Estimated Volume of Infil				0.00 bbls					
			• •	4.40 DDIE					
Estimated Total Volume o				0.60 m³					
Estimated Total Volume of	of Infiltrated oil, V <sub>inf</sub>			3.80 bbis					
able of average depth of c ipill Factors from USCG FOG	oil on water based on coloration (2000 Edition)	Link to Coverage Visual	ı						
		Percentage coverage (%)	V-h (2)						
Barely Visible	Thickness (mm) 0.00004		Volume (m3) 0,0000						
Silvery	0.00008		0.0000						
Slight Color	0.00015		0.0000						
Bright Color	0.0003		0.0000						
<u>Dull</u>	0,001		0.0000						
<u>Dark</u>	0.002		0.0000						
Black oil	0.1	<u> </u>	0.0000						
Emulsion (30% Oil)	1 Percent Total:		0.0000						
<u> </u>	Percent rotal:	0%	0.0000						
Estimated Volume of oil o	on open water, V <sub>est</sub>			0.00 m³					
Estimated Volume of oil o	on open water, V <sub>wet</sub>			0.00 bbis					
iation of evaporated volu	im <del>s</del>								
<del> </del>	Evaporation Factors (E-Factor) for S	SPDC Crude oil							
Residence time	of spilled oil (days on site)	Oil ty	/pe						
	o. opoc o (days or. one)	Bonny Light	Bonny Medium						
	< 1 day	10%							
	1-7 days > 7 days	25% 40%							
	uajv	1 4070	1 2976	l					
				No 🔻					
Was oil recovery before Ji\	/ completion done before JIV date?								
•	•			5.37 bb/s					
Estimated volume available	•			5.37 bbis					
Estimated volume available	•								
Was oil recovery before JiN Estimated volume available E-factor Estimated Volume of eva	e for evaporation			5.37 bbis					
Estimated volume available	e for evaporation porated oil, V <sub>evap</sub>			5.37 bbls					

	THE SHE	LL PETRO	OLEU	IM DEVE	LOPMENT	COME	PANY OF N	IGERIA L	IMTED.	
INT INVI	ESTIGATION	N REPORT	FOR	INCIDENT	NO: 125	7852	O JIV rep	ort S/N:	กกลก	1
	CIDENT INF								00.70	
20.	Impacted Ar	ea Details								
	-				~ 1 U A					
	• To	tal calculated	d area	of impact_	<u>0.1114</u>				_	
	• Im	pact within S	SPDC !	R.O.W	<u> </u>					
	• lm	pact outside	SPDC	R.Q.W	No		<u>-</u>			
21.	Volume of o	il recovered	l befor	re complet	ion of JIV	$(V_{recJ})$ :				
				Reco	vered oil V <sub>re</sub>	;;;	NIL		Barrels	]
Co	ontrolled reco	overy/evacu	iation	from sour	ce with no i	impact to	o environmen	ıt:		_
				MIL	Barrels	7				
				<del></del> -			<del>_</del>	·		_
22.	Net Estimat	ed Spilled	<u>Volun</u>	ne V <sub>Ert</sub> (bb	<u> ls)*</u> =					
		•			1					
			$\neg$	. 16	14 M	<b>እ</b> ጹ ድ‹	<b>-S</b>			
			I	, 0	<b>₩</b>	** *				
Eatin.	And Dama-A-	1 37 - 1 44	37 O	1.1.			ertes	<u> </u>		
ESHIII	ted Reported	i A Offilise	V <sub>rep</sub> (D	DIS !=	<i>Y</i> -	1/2 1-1	22210			
			<del></del>			0/1/	<del>UCCAN</del>			
*Notes:										
740/63.	Volume estima	tion was dane u	icina an .	ercel hased to	al isan attachae	l Con detaile	on the calculation	1		
•		ed volume is an			or face intercrea	i jor ucions	On the cancadation	U		
Wr.	ite other relevant	notes taken inte	o conside	eration for est	imating the snit	led in the b	av below:			
				,			on below.			
								-		
					_					
			_							
							<u> </u>		<del></del>	
Calculati	ion of the respect	ive estimated vo	hume is i	to be done on .	site as for as pr	acticoble w	sing the new spill	valiane estion	itian software o	, ,
Conversi	on of m³ to barre	ls is Volume (m.	3) x 6.29	); **Round up	estimated volu	ine to next	whole number usir	rounne estima n <b>e the foll</b> owi	aion sojiware a na rules:	131
•		ne in excess of						<b>0</b> ,		
•	Any spill volun	ie in less than	1 bbl	is rounded u	ip to the next 0. i	I bbl.				
					•					
	_				•					
	Examples:				Reported vol Reported vo	lume = 16 E				

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

Calculated volume = 0.01 bbl ----- Reported volume = 0.1 bbl.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1298630 JIV report S/N: 00801

### 23. GENERAL STATUS OF THE SITE

A.	Joint investigation of the incident site found that there is no residual impact after the initial response and JIT therefore recommend that the site be closed out
В.	Investigation of the incident site showed that there is residual impact on site requiring further works

### 24. REPRESENTATIVES

This report was filled, agreed and signed by the following joint investigation representatives:

- Department of Petroleum Resources [DPR]:
- National Oil Spill Detection and Response Agency [NOSDRA]
- State Ministry of Environment [SME]:
- Shell Petroleum Development Company [SPDC]:
- Signatories agree with reported findings:
- Separate DPR form has been filled out with same findings

Tick as applicable

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1298530 JIV report S/N: 00801

25. Appendix 1: Overview sketch of the site

