

Overview: Part of spill impact on Ubie Well 4S Flowline Right of Way at Idu-Ekpeye. Picture was taken during Joint Investigation of 18th September 2014.



<u>Close-up:</u> Cut section of missing flowline on Ubie Well 4S Flowline at Idu-Ekpeye. Picture was taken during Joint Investigation of 18th September 2014.

1



<u>Close-up:</u> Hacksaw cuts on Ubie Well 4S Flowline at Idu-Ekpeye. Picture was taken during Joint Investigation of 18<sup>th</sup> September 2014.