THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LI	MTED.
JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1254536 JIV report S/N: (0676
(Note: As practicable as possible the JIT report is to be signed in the field by all the participating p	
A. GENERAL INFORMATION:	
1. Spill incident Number: 1254-536 2. Type of incident* OIL SF	
3. Name of Location 20" OPUKUSHI - BRASS (REEK PIPEL	
4. Name of nearest community PERETOURUGBENE S. State: BAYELSA 6. LGA EKEK	ZEMOR
7. Type of Production facility/Installation OIC PIPELINE 8. Asset owner/District PIPE	LINES
B. INCIDENT INFORMATION:	
9. Details of incident a. Date of incident: 19 TH SEPTEMBER, 2014	
b. Start date/time of investigation: 28 TH OCTOBER, 2014 AT 120	otes
c. Investigation End date: 28TH OCTOBER, Actual investigation duration, days: 1	DAY_
d. Description of spill point environment	
·	
☐ Firmed soil ☐ Loose soil ☐ Recently excavated are: ☐ Under water ☐ Exposed pipe surface	a
☐ Under water ☐ Swampy ☐ Exposed pipe surface ☐ Drill Rig	
Additional observations around the spill point: UPON EXCAVATION, A 4"	GANFD
WELD-ON ILLEGAL HOT-THE VALUE WITH GALVANI	ZED DIRE
FITTING WAS OBSERVED MELDED ON THE 20" OF	PUKUSHI TO
BRAST CREEK PIPELINE AT 12 0° CLOCK POSITION.	W. Colored
e. Description of leak point (tick as applicable); Drilled hole Hack saw cut Tear (ر,
☐Complete Rupture ☐ inward dent, ☐Well head tampering	
Failed Weld-on illegal hot tap valve, Failed Clamp Missing Pipeline/Flow	line
Crude oil theft (illegal bunkering) point,	with Clamp
☐ Third party tampering with valve setting, ☐ Third party tampering	
☐Corrosión ☐Saver-pit over flow, ☐Surge vessel overflow,	
☐Bulging Outward ☐Flare System/Bund wall failure ☐Accidental 3	
impact 🗆 Valve Failure 🔻 🗀 com unit failure 🔻 🗀 Cold	vent
Relief valve failure Others (specify)	
f. Incident caused by:	
The state of the s	
☐ Third party interference (Sabotage☐; crude theft☐; Line theft☐; Accidental 3 rd party date ☐ Operational ☐ Others (including Mystery spills)	mage□)

^{*}This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction c) Encroachment f) Fire,

		PETROLEUM D							
DINT INVESTI	GATION REI	PORT FOR INCI	DENT NO: <u> </u>	154	<u> 536</u> ,	IV report S/	м: 00	676	
g. Spi	Measuring Northing:	unit		klie 	ST C Easting: C		•	<u>.</u>	٦
	11	04794.	60			3597	61.5	. G	
									\exists
	<u> </u>								,-
									٠.
	ASSESSMEN								
10.	Туре о	of environment:				_			
	Land	⊠ Swamp	□Water	□Se	asonal swa	mp□Shoreli	nc/Waterfi	ront	
	i. Type of	Cenvironment to w	hich oil has s	pread:					
Е	Land	⊠Swamp	□water	□Ri	ver (identif	y)		•	
:	ii. Weathe	r condition	•						
	Rain stance from th	☑Sunny ne nearest sensitive	□Dry habitat	□Wet	□Win	dy 🗆	lHot [□cool	
0 0 0	Government Drinking wat Built up are Farmlands Fish Farm/F Fishing net Others (spec	a Pond	gnated protec	ted area	[[[[,m] ,m] ,m] ,m] ,m]	NON	E WITH VICINI	れいて
12. Co	ontainment me	easures put in place	;						
	⊒Booms ⊠Others: <u>C0</u>	□Trench FPER-DAM	□Dyke	□na	atural depre	ession E]Pit	□Non	ıc
13. A	ny pictures or	video coverage?			KY)	[N]			
14. F	urther respons	se/repair initiated a	is at the time	of JIV?	W	[N]			
If yes to iten	n 14, give brief	description: BUI	ND FLA	NGING	TOF	THE 11	1 CIDE	UT P.O 11	<u>N</u> 7
		out By				JTENAN	CE TO	EAM.	
15. W	as there any d	lisruption to the in	vestigation?		[Y]	NOT			
If yes to ite	em 15 give bri	ef description:	OT AP	PLI <i>C</i> A	BLE				_
			 						_

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED. JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1254536 JIV report S/N: 00676

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

16. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
	NONE W	THIN	AREA	OF IMP	7
	740.40	117 (7 (7 170-27 7	07 171() 7	

17. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
	LUDALS	= 1.11-7111	0 1 /2	- 1 No	100.000	
	10 0146	- MI 1119	N-MK	C71-U	-MYHC	
						_


18. Fish/Nets/Ponds

S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
<u> </u>	1 8 , 4	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		144.04.0=
	NONC	NITHIN THE	=/+ -()/	-IMPACI
	-			

19. Others (Specify) i.e. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
	NONE	WITHNA	REA (F-IMPACT
	14 01- 0		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	- IMPTICI

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1)



20"

FROM OPHKUSHI TO BRASS CREEK

20" OPUKUSHI-BRASS CLEEK PIPELINE AT PERETOURUGBENE

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMTED.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1254536 JIV report S/N: 00676

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION 20. Impacted area boundary Coordinates (If more, Print and attach as an appendix)

MINNA (WEST BEIT)

	MINNA (1	JEST 16EU)
S/N	Northing (m)	Easting Cm)
1	104791.83	359759.51
2	104796.98	359760,81
3	104796.40	359764.01
4	104791.17	359759·51 359760·81 359764·01 359762·89
		
	:	
<u> </u>		
<u> </u>		
	 	
	 	
 		
<u> </u>	 	
ļ		
<u> </u>	 /	
	/	
/		
1/		

ESTIMATION OF OIL SPILL VOLUME

Α	OIL SPI	LLED ONSHORE	VOFFSHORE (Leak stopped at	source)		
	<u>Impacted</u>	Area Details				10.00
	Tota	il Calculated Area o	f Impact			18.00 m²
	i Impe	act within SPDC R.O.	W			m²
	ii Impa	act outside SPDC R.C	D.W			m²
1	Volume o	of all recovered befo	re completion of JIV (V,-c)			
	-	nated Recovered oil (bbls
	Esti	mated Rocovered of	l (Not) V _{ree}		<u></u>	0.00 bbls
			<u> </u>	·	-	
2			sidual volume on site			
		•	of free phase oil (on land or confine	d water body)		
		I area occupied by po				18.00 m²
		age depth of pool of	=			0.002 m
	jii Emu	Isification factor	(If applicable, else 0%)			40 %
	Esti	mated Volume of po	ol of free phase oil, V _{pool}			0.02 m³
	Esti	mated Volume of po	ol of free phase oil, V _{pool}			0.14 bbls
				107 1		
			ed volume of inflitrated oil in the sol	i (V _{Int})		
			at spili point (V _{h/a})			m²
		I area covered by the		. 41		
		•	on above leaking facility i.e. pipeline/flor	Mine		<u></u>
	III Soil		19			Sity or sandy clay ▼
	iy P₄ (€	effective porosity of th	le soli)			12 %
	v Can	se of spill				Third party interference
	v Cab	so or apm			_	
	vi (r infiltration below the leaking point on p			
		Incident Date	JIV Date	Days on Site		
		9/19/2014 13:40	10/28/2014 14:45	39		
	If		rational , use 1 week as worst case where 'days on site' exceeds 7.	7		
			tofiloston of all topon to contain well.	luana va lima		7
		Callbran	Infiltration of all types in various soil		nd loval	-
	Oit t	Soil type	Approximate time to reach Sand	Loam	Clay	┪
		ny Medium	3 weeks	3 years	> 10 years	7
		ny Light	2 days	2 months	> 10 years	
	ماها وي					Bonny Medium
	vii Oil ty		and the state of t	ultaa		0.011m
	VIII AVEI	age depth of insutratio	on below leaking facility i.e. pipeline/flow	Mine		0.011
	ix Tota	l depth below ground	surface of infiltration of oil			0.011 m
						0.00 m³
		mated Volume of in mated Volume of In				0.00 bbis
	E301	mated <u>volume of thi</u>	maded on v Mrs.			
	2 Volu	ime of infiltrated oil	at second spill point [if applicable]	(V _{hfb})		
		I area covered by the				m²
			on above leaking facility i.e. pipeline/flo	Mine		<u>m</u>
	fii Soil	typo				Silty or sandy clay
	iy P. (e	affective porosity of th	e soil)			12 %
	v Aver	rage depth of infiltration	on below leaking facility i.e. pipeline/flow	Mine		0.011 m

JOINT INVESTIGATION REPORT SPILL VOLUME ESTIMATE FOR INCIDENT NO: 1254536

vi Total depth below ground surface of infiltration of oil				0.011 m		
Estimated Volume of In	filtrated oli, V _{Mb}			0,00 m³		
Estimated Volume of Int				0.00 bbis		
1 Total Area covered by the	Volume of infiltrated oil outside immediate spill point(s) region (V_{infe}) Total Area covered by the oil (infiltration) Total Area of the pool of free phase oil in touch with soil					
ifi Soil type				m² Sitty or sandy day ▼ j		
iv P. (effective porosity of th	e soil)			12 %		
	and surface of infiltration of cil			0.011 m		
Estimated Volume of Inf				0.00 m³		
Estimated Volume of Inf	iltrated oil, V _{info}		<u> </u>	0,00 bbls		
i Total Area covered by the ii Total Area of the pool of fi	4 Volume of Infiltrated oil outside immediate spill point(s) region (superficial impact, V _{inf d}) i Total Area covered by the oil (infiltration) ii Total Area of the pool of free phase oil in touch with soil iii Average depth below ground surface of infiltration of oil 0.011 m					
Estimated Volume of Inf	Estimated Volume of Inflitrated oil, V _{Md}					
Esumsted volume of int	ilinaton oli, A ^{FA} 4			0.00 bbls		
Estimated Total Volume Estimated Total Volume	of Infiltrated oil, V _{inf} of Infiltrated oil, V _{inf}			0.00 m³ 0.00 bbls		
I Total area of oil on open w ii Table of average depth of	oil on water based on coloration	iard coloration	1	m²		
Spill Factors from USCG FOG ((2000 Edition)	Aid Percentage coverage	<u> </u>	1		
	Thickness (mm)	(%)	Volume (m3)			
Barely Visible	0.00004		0.0000			
Silvery	0.00008		0.0000			
Slight Color	0.00015		0.0000			
Bright Color	0.0003		0.0000			
<u> Dull</u>	0.001		0.0000			
Dark Black oil	0,002		0,0000			
Emulsion (30% Oil)			0.0000			
Entrision (30% Off)	Percent Total:	0%	0,0000			
		U%]	0.0000			
Estimated Volume of oil	on open water, V _{wet}			0.00 m ³		
Estimated Volume of oil	on open water, V _{wat}	· · · · · · · · · · · · · · · · · · ·		0.00 bb(s		
				· —		

3 Calculation of evaporated volume

Evaporation Factors (E-Factor) for SPDC Crude oil					
Residence time of spilled oil (days on site)	Oil t	уре			
Tresidence time of spines on (days off site)	Bonny Light	Bonny Medium			
< 1 day	10%	5%			
1-7 days	25%	15%			
>7 days	40%	25%			

Yes

JOINT INVESTIGATION REPORT SPILL VOLUME ESTIMATE FOR INCIDENT NO: 1254536

il Estimated volume available for evaporation	0.14 bbis
iii E-factor	25 %
Estimated Volume of evaporated oil, V _{evap}	0.05 bbls
Net Total Estimated Spilled Volume, Ven	0.18 bbls

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMTED.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1254536 JIV report S/N: 00676 G. INCIDENT INFORMATION:

20	Impacted	Area	Details
ZU.	HIIDacicu	nica	Derails

•	Total calculated area of impact 0.0018H4	
•	Impact within SPDC R.O.W	
•	Impact outside SPDC R.O.W	
21. Volume	e of oil recovered before completion of JIV (Vreel):	
•	Recovered oil Vices NIL	Barrels
Controlled	ed recovery/evacuation from source with no impact to environment:	
	NIL Barrels	

322 Nef Estimated Spilled Volume Ven	obls)		"这个数数 "
		18 BBL	
the first facilities of the same of the sa	N. A. C.	State of the state	and a second
Estimated Reported Volume** Vrep(bbls)=	0.2 8	3BL	

*Notes:

Volume estimation was done using an excel based tool. (see attached for details on the calculation)

Reported spilled volume is an estimate Write other relevant notes taken into consideration for estimating the spilled in the box below:

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site;

Conversion of m² to barrels is Volume (ni3) x 6.29; **Round up estimated volume to next whole number using the following rules:

Any spill volume in excess of | 1 bbi | is rounded up to the next whole number.

I bbl is rounded up to the next 0.1 bbl. Any spill volume in less than

Calculated volume = 15.3 bbl ----- Reported volume = 16 bbl Examples: Calculated volume = 0.35 bbl ----- Reported volume = 0.4 bbl Calculated volume = 0.01 bbl ------ Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the HV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMTED. JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1254536 JIV report S/N: 00676 23. GENERAL STATUS OF THE SITE

A. Joint investigation of the incident site found that there is no residual impact after the in response and JIT therefore recommend that the site be closed out	iitial
B. Investigation of the incident site showed that there is residual impact on site requiring fur works	rther

24. REPRESENTATIVES

	investigation representatives:

- Host Community:
- Department of Petroleum Resources [DPR]: □
- National Oil Spill Detection and Response Agency [NOSDRA]:
- State Ministry of Environment [SME]:

 □
- Nigeria Police Force [NPF]:

 ✓
- Shell Petroleum Development Company [SPDC]: □
- Signatories agree with reported findings: <a>S
- Separate DPR form has been filled out with same findings □

Tick as applicable

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMTED.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1254-53 C JIV report S/N: 00676

25. Appendix 1: Overview sketch of the site

Location: 20	OPUKUSHI - BRASS CREEK PIPELINE AT PERETI	OU RUGBENE
	-20" OPUKUPHT TO BRASS CREEK PIPELINE	S E
THCK BUST		BWH.
王(王)	COFFER-DAM -> SPILL POINT WITH FREE PHASE CRUDE OIL!	为 ck
CK Bult		Bult
更	SPDC - RIGHT OF WAY-	