THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMTED. JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1380472 JIV report S/N: 00839 (Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties) A. GENERAL INFORMATION: 2.Type of incident* Di 1. Spill incident Number: UMUECHEM - NKPOKU 4. Name of nearest community OMUNWFI 5. State: RIVERS 6. LGA IKWERRE 7. Type of Production facility/Installation OIL PIPELINE 8. Asset owner/District PIPELINE **B. INCIDENT INFORMATION:** 9. Details of incident a. Date of incident: 14 TH APRIL, 2015 APRIL, 2015/13:00Hours b. Start date/time of investigation: 16TH c. Investigation End date: d. Description of spill point environment Loose soil Recently excavated area ☐Firmed soil Under water Swampy Exposed pipe surface ☐ Well Platform (on Water) ☐Drill Rig Additional observations around the spill point: SPILL WAS OBSERVED OCCURRED ON AN ONGOING REMEDIATION SITE. BESIDE WHICH WAS A YELLOW TARPAULIN MATERIAL WITH SOME SAND BAGS ON TOP OF IT, LEFT ON SITE BY UNKNOWN PERSON(S). e. Description of leak point (tick as applicable); Hack saw cut Tear (Drilled hole ☐Well head tampering □Inward dent, Complete Rupture ☐Missing Pipeline/Flowline □ Failed Weld-on illegal hot tap valve, □ Failed Clamp ☐ Third party tampering with Clamp ✓ Crude oil theft (illegal bunkering) point, Third party tampering with valve setting, ☐ Third party tampering with flange, ☐Surge vessel overflow, ☐ Corrosión ☐ Saver-pit over flow, □Flare System/Bund wall failure □Accidental 3rd party equipment ☐Bulging Outward Com unit failure ☐Cold vent □ Valve Failure

Others (specify)

Third party interference (Sabotage□; crude theft □; Line theft□; Accidental 3rd party damage□)

Others (including Mystery spills)

Relief valve failure

f. Incident caused by:

☐ Operational

^{*}This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire,

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1380472 JIV report S/N:

	Northing	LLATITU	(30	•	Easting:	(لت،۸۵	WITUDE	-)	
	1	4 .9830	4			7.0	239	3	
					<u>.</u>				
RIS	K ASSESSM	ENT .			-	• • •			
1	0. Тут	e of environment:							
	Land	☐Swamp	□Water	□Se	asonal sw	/amp□She	oreline/Wat	erfront	
	i. Type	e of environment to	which oil has	spread:					
	Land	☐Swamp	□Water	□Ri	ver (ident	ify)			
	ii. Wea	ther condition			·			•	
11.	Rain Distance from	Sunny the nearest sensit	Dry ive habitat	□Wet	□wi	indy	□Hot	Псо	ol
		ls n/Pond iet	esignated prote	cted area	[[[[,m] ,m] ,m] ,m] ,m]	IPA CTE	р ву	SPILL.
12.	Containment	measures put in pla	ace;						
	Booms Others:	□Trench	DDyke ERVED	ØNa ARøun	tural dep		ØPit INT.		□None
13.	Any pictures	or video coverage?	•		[🗘	[N]			
14.	Further resp	onse/repair initiate	d as at the time	of JIV?	[\(\forall \)	[N]			
	item 14, give br	ief description:	CTEN C	M. THE	AFT	ECTEN	<u>Gert</u>	on 1	DE PIPEL
<u>†</u>	CLAMPIN	I.G.							
		42 22 5 24	investigation?		[X]	' [N]			

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1380472 JIV report S/N: 00839

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

16. Structures / Properties

S/N	Type of Structures	i	Description	Size		Number	:	Comments	
N	ONE '	\mathcal{M}	1 T F# 11	1	AR	FΑ	0F	IMPACT	
L	7. 0/				-				

17. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
-1,	CASSAVA		/		WITHIN AN	WITHM
2	MAIZE				UMPACTED	SPILL -
3	PALM TREES	<u> </u>	ļ	<u> </u>	AREA OF	IMPACTED
L			<u> </u>		0.92 Ha	"AREA (FARM)


18. Fish/Nets/Ponds

S/N	Fish/Nets/Ponds	Description		Quantity/Size	Comments
11	aur 1	I 11	\	X 0-	1.00-
IZ	UNE	MIHIN	TIKE	A UF	MPACT
					-

19. Others (Specify) i.e. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
M	ONE W	ATHIN ARE	A OF	IMPACT

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detail report of the leak point should be contained in the



JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1380472 JIV report S/N: 00839

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION 20. Impacted area boundary Coordinates (If more, Print and attach as an appendix)

S/N	Northing (LATTUBE)	Easting (LONGITUDE)
	:	
		7
		<u>Cis</u>
	l W	
	7	* 4
	5	X
	1	\\ \tag{\alpha} \\ \alpha
	<u> </u>	(A +
	, i	12 7 3
	<u> </u>	W Z O
	(, 0	* Z Z
	1	T 7
	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
	C	<u> </u>
		6.7
		1 A
		
	•	
		-
		<u> </u>
	 	

8"UMUECHEM-NKPOKU DELIVERY LINE AT OMUNWEI APPENDIX A: IMPACTED AREA COORDINATES INCIDENT NUMBER:1380472

WGS 84

POINT LATITUDE L	ONGITUDE.
------------------	-----------

COORDINATES OF SUPERFICIAL IMPACT ON FARMLAND

DINAT	ES OF SUPE	RFICIAL IMF
242	4.98318	7.02418
243	4.98305	7.02446
244	4.98344	7.02476
245	4.98331	7.02513
246	4.98310	7.02533
247	4.98253	7.02497
248	4.98241	7.02466
249	4.98240	7.02466
250	4.98277	7.02409
241	4.98331	7.02393
251	4.98274	7.02404
252	4.98280	7.02378
253	4.98289	7.02377
254	4.98300	7.02362
255	4.98287	7.02354
256	4.98290	7.02351
257	4.98296	7.02355
258	4.98296	7.02355
259	4.98302	7.02357
260	4.98363	7.02261
261	4.98375	7.02238
262	4.98363	7.02236
263	4.98361	7.02240
264	4.98356	7.02238
265	4.98358	7.02234
266	4.98302	7.02225
267	4.98302	7.02231
268	4.98297	7.02231
269	4.98297	7.02225
270	4.98278	7.02222
271	4.98268	7.02222
272	4.98270	7.02227
273	4.98265	7.02226
274	4.98265	7.02223
275	4.98240	7.02221
276	4.98239	7.02218
277	4.98268	7.02219
278	4.98367	7.02230
279	4.98402	7.02251
280	4.98401	7.02254
281	4.98386	7.02246
282	4.98355	7.02288
~~~	4 00057	7.00000

283 4.98357 7.02288

284	4.98354	7.02291
285	4.98351	7.02291
286	4.98306	7.02366
287	4.98313	7.02370
288	4.98316	7.02366
289	4.98322	7.02376
290	4.98317	7.02381
291	4.98319	7.02388

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1380472 JIV report S/N: 00839

G. INCIDENT INFORMATION:

20	Impacted	Атез	Detaile
÷۷.	mmacicu	$\Delta u \cup a$	Delans

•	Total calculat	ed area of impa	1.404	વ	
•		SPDC R.O.W			
•	Impact outsid	e SPDC R.Q.W	785		
1. Volume	of oil recover	ed before comp	oletion of JIV (V	reeJ):	
	-	c R	ecovered oil Vrees:	188	Barrels
Controlled	recovery/eva	cuation from s	ource with no im	pact to environment:	
_		NII.	Barrels		

22. Net Estimated Spilled Volume V _{ER} (b)	bls)* = 336 - 33	
Estimated Reported Volume** V _{rep} (bbls)=	337 BARRELS	

*Notes:

Volume estimation was done using an excel based tool (see attached for details on the calculation)
 Reported spilled volume is an estimate

Write other relevant notes taken into consideration for estimating the spilled in the box below:

IN ESTIMATING THE SPILLED VOLUME, PARTICULARLY WITH RESPECT TO VOLUME OF OIL INFILTRATION IN SOIL, THE LOOSE PARTICLE NATURE OF THE SOIL WITHIN SPILL POINT ENVIRONMENT WAS TAKEN COGNIZANCE OF (BEING AN ONGOING REMEDIATION SITE) BY CARRYING OUT TRIAL PIT EXCAVATION IN ORDER TO VERIFY INFILTRATION DEPTH IN THE SOIL.

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of  $m^t$  to burrels is Volume (m3) x 6.29; **Round up estimated volume to next whole number using the following rules:

Any spill volume in excess of 1 bbl is rounded up to the next whole number.

Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1380472 JIV report S/N: 00839

#### 23. GENERAL STATUS OF THE SITE

A.	Joint investigation of the incident site found that there is no residual impact after the initi response and JIT therefore recommend that the site be closed out	al
В.	Investigation of the incident site showed that there is residual impact on site requiring furth works	ег

#### 24. REPRESENTATIVES

	signed by the following joint investigation representatives
This concert was tilled agreed an	cionea ny tae indowina inini lavesdy allon ledicsculauves

- Host Community:
- Department of Petroleum Resources [DPR]:
- National Oil Spill Detection and Response Agency [NOSDRA]: IN
- State Ministry of Environment [SME]:
- Nigeria Police Force |NPF|: □
- Shell Petroleum Development Company [SPDC]:
- Signatories agree with reported findings:
- Separate DPR form has been filled out with same findings

Tick as applicable

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1380472 JIV report S/N: 00839

25. Appendix 1: Overview sketch of the site

