

**THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED.**

**JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1383004 JIV report S/N: 00876**

*(Note: As practicable as possible the JIV report is to be signed in the field by all the participating parties)*

**A. GENERAL INFORMATION:**

1. Spill incident Number: 1383004 2. Type of incident\* OIL SPILL  
 3. Name of Location 16" Nun River - Kolo Creek Pipeline  
 4. Name of nearest community OPOROMA 5. State: BAYELSA 6. LGA SOUTHERN IJAW  
 7. Type of Production facility/Installation OIL PIPELINE Asset owner/District PIPELINE

**B. INCIDENT INFORMATION:**

9. Details of incident  
 a. Date of incident: 17<sup>TH</sup> APRIL, 2015  
 b. Start date/time of investigation: 24<sup>TH</sup> APRIL, 2015 / 10:30 AM.  
 c. Investigation End date: 25<sup>TH</sup> APRIL, 2015 Actual investigation duration, days: TWO (2) DAYS.  
 d. Description of spill point environment

- |   |  |   |
|---|--|---|
| <input type="checkbox"/> Firmed soil              | <input checked="" type="checkbox"/> Loose soil | <input checked="" type="checkbox"/> Recently excavated area |
| <input type="checkbox"/> Under water              | <input checked="" type="checkbox"/> Swampy     | <input type="checkbox"/> Exposed pipe surface               |
| <input type="checkbox"/> Well Platform (on Water) |  | <input type="checkbox"/> Drill Rig                          |

Additional observations around the spill point:

**e. Description of leak point (tick as applicable);**

- |   |   |   |
|---|---|---|
| <input type="checkbox"/> Drilled hole                               | <input checked="" type="checkbox"/> Hack saw cut        | <input type="checkbox"/> Tear (_____).                              |
| <input type="checkbox"/> Complete Rupture                           | <input type="checkbox"/> Inward dent,                   | <input type="checkbox"/> Well head tampering                        |
| <input type="checkbox"/> Failed Weld-on illegal hot tap valve,      | <input type="checkbox"/> Failed Clamp                   | <input type="checkbox"/> Missing Pipeline/Flowline                  |
| <input type="checkbox"/> Crude oil theft (illegal bunkering) point, |   | <input type="checkbox"/> Third party tampering with Clamp           |
| <input type="checkbox"/> Third party tampering with valve setting,  |   | <input type="checkbox"/> Third party tampering with flange,         |
| <input type="checkbox"/> Corrosion                                  | <input type="checkbox"/> Saver-pit over flow,           | <input type="checkbox"/> Surge vessel overflow,                     |
| <input type="checkbox"/> Bulging Outward                            | <input type="checkbox"/> Flare System/Bund wall failure | <input type="checkbox"/> Accidental 3 <sup>rd</sup> party equipment |
| impact <input type="checkbox"/> Valve Failure                       | <input type="checkbox"/> com unit failure               | <input type="checkbox"/> Cold vent                                  |
| <input type="checkbox"/> Relief valve failure                       | <input type="checkbox"/> Others (specify) _____         |   |

**f. Incident caused by:**

- ☒ Third party interference (Sabotage ☒, crude theft ☐; Line theft ☐; Accidental 3<sup>rd</sup> party damage ☐  
☐ Operational ☐ Others (including Mystery spills) \_\_\_\_\_

*\*This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire,*

**THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED.**

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1383004 JIV report S/N: 00876

g. Spill point coordinates

|                |                  |               |                   |
|----------------|------------------|---------------|-------------------|
| Measuring unit |                  | <u>WGS 84</u> |                   |
| Northings:     | <u>CLATITUDE</u> | Easting:      | <u>CLONGITUDE</u> |
|                | <u>4.81343</u>   |               | <u>6.11876</u>    |
|                |                  |               |                   |
|                |                  |               |                   |
|                |                  |               |                   |

**C. RISK ASSESSMENT**

10. Type of environment:

☐ Land ☒ Swamp ☐ Water ☐ Seasonal swamp ☐ Shoreline/Waterfront

i. Type of environment to which oil has spread:

☐ Land ☒ Swamp ☐ Water ☐ River (identify) \_\_\_\_\_

ii. Weather condition

☐ Rain ☒ Sunny ☒ Dry ☐ Wet ☐ Windy ☐ Hot ☐ Cool

11. Distance from the nearest sensitive habitat

☐ Government reserved and designated protected area [ ,m]  
☐ Drinking water source [ ,m]  
☐ Built up area NONE SEEN [ ,m]  
☐ Farmlands WITHIN VICINITY [ ,m]  
☐ Fish Farm/Pond [ ,m]  
☐ Fishing net [ ,m]  
☐ Others (specify). [ ,m]

12. Containment measures put in place;

☐ Booms ☐ Trench ☒ Dyke ☒ Natural depression ☐ Pit ☐ None  
☐ Others: \_\_\_\_\_

13. Any pictures or video coverage?

Y [N]

14. Further response/repair initiated as at the time of JIV?

Y [N]

If yes to item 14, give brief description:

RECOVERY ACTIVITIES ONGOING.  
REPAIR WAS DONE BY CLAMPING.

15. Was there any disruption to the investigation?

[Y] N

If yes to item 15 give brief description:

NOT APPLICABLE.

**THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED.**

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1383004 JIV report S/N: 00876

**D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL**

**16. Structures / Properties**

| S/N | Type of Structures         | Description | Size | Number | Comments |
|-----|----------------------------|-------------|------|--------|----------|
|     | NONE WITHIN AREA OF IMPACT |             |      |        |          |

**17. Crops/Economic Trees**

| S/N | Type of crops              | Young | Medium | Matured | Quantity | Comments |
|-----|----------------------------|-------|--------|---------|----------|----------|
|     | NONE WITHIN AREA OF IMPACT |       |        |         |          |          |

**18. Fish/Nets/Ponds**


| S/N | Fish/Nets/Ponds            | Description | Quantity/Size | Comments |
|-----|----------------------------|-------------|---------------|----------|
|     | NONE WITHIN AREA OF IMPACT |             |               |          |

**19. Others (Specify) i.e. Animal Traps**

| S/N | Others                     | Description | Quantity/Size | Comments |
|-----|----------------------------|-------------|---------------|----------|
|     | NONE WITHIN AREA OF IMPACT |             |               |          |

**E. GRAPHIC DESCRIPTION OF LEAK POINT** (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1)

SECTION OF 16" MUNI RIVER - KOLO CREEK PIPELINE AT OPOROMIA  
SHOWING POSITION OF HALL SAW CUT AT 2 O'CLOCK POSITION.



**THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED.**

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1383004 JIV report S/N: 00876

**F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION**

20. Impacted area boundary Coordinates (If more, Print and attach as an appendix)

WGS 84

| S/N | Northings<br>(EASTING) <del>(LATITUDE)</del> | Easting<br><del>(LATITUDE)</del> (NORTHING) |
|-----|--|---|
|     | 6.11843                                      | 4.81318                                     |
|     | 6.11845                                      | 4.81313                                     |
|     | 6.11876                                      | 4.81335                                     |
|     | 6.11872                                      | 4.81345                                     |
|     | 6.11876                                      | 4.81347                                     |
|     | 6.11879                                      | 4.81339                                     |
|     | 6.11980                                      | 4.81381                                     |
|     | 6.11989                                      | 4.81385                                     |
|     | 6.12000                                      | 4.81388                                     |
|     | 6.12016                                      | 4.81396                                     |
|     | 6.12032                                      | 4.81399                                     |
|     | 6.12044                                      | 4.81404                                     |
|     | 6.12043                                      | 4.81404                                     |
|     | 6.12047                                      | 4.81400                                     |
|     | 6.12050                                      | 4.81410                                     |
|     | 6.12048                                      | 4.81412                                     |
|     | 6.12053                                      | 4.81413                                     |
|     | 6.12057                                      | 4.81410                                     |
|     | 6.12066                                      | 4.81413                                     |
|     | 6.12070                                      | 4.81409                                     |
|     | 6.12046                                      | 4.81414                                     |
|     | 6.12050                                      | 4.81416                                     |
|     |  |   |
|     |  |   |
|     |  |   |
|     |  |   |

**THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED.**

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1383004 JIV report S/N: 00876

**G. INCIDENT INFORMATION:**

**20. Impacted Area Details**

- Total calculated area of impact 0.26Ha
- Impact within SPDC R.O.W YES
- Impact outside SPDC R.O.W YES

**21. Volume of oil recovered before completion of JIV ( $V_{rec}$ ):**

|                           |           |         |
|---------------------------|-----------|---------|
| Recovered oil $V_{rec}$ : | <u>10</u> | Barrels |
|---------------------------|-----------|---------|

Controlled recovery/evacuation from source with no impact to environment:

|            |         |
|------------|---------|
| <u>NIL</u> | Barrels |
|------------|---------|

**22. Net Estimated Spilled Volume  $V_{est}(bbls)^* =$**

71.46 BARRELS

**Estimated Reported Volume\*\*  $V_{rep}(bbls) =$**

72 BARRELS

**\*Notes:**

- Volume estimation was done using an excel based tool. (see attached for details on the calculation)
- Reported spilled volume is an estimate

Write other relevant notes taken into consideration for estimating the spilled in the box below:

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of  $m^3$  to barrels is Volume ( $m^3$ )  $\times$  6.29; \*\*Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of: 1 bbl is rounded up to the next whole number.
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl ----- Reported volume = 16 bbl  
 Calculated volume = 0.35 bbl ----- Reported volume = 0.4 bbl  
 Calculated volume = 0.01 bbl ----- Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

**THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED.**

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1383004 JIV report S/N: 00876

**23. GENERAL STATUS OF THE SITE**

|  |
|--|
| A. Joint investigation of the incident site found that there is no residual impact after the initial response and JIT therefore recommend that the site be closed out <input type="checkbox"/> |
| B. Investigation of the incident site showed that there is residual impact on site requiring further works <input checked="" type="checkbox"/>   |

**24. REPRESENTATIVES**

This report was filled, agreed and signed by the following joint investigation representatives:

- Host Community: ☒
- Department of Petroleum Resources [DPR]: ☒
- National Oil Spill Detection and Response Agency [NOSDRA]: ☒
- State Ministry of Environment [SME]: ☒
- Nigeria Police Force [NPF]: ☒
- Shell Petroleum Development Company [SPDC]: ☒
- Signatories agree with reported findings: ☒
- Separate DPR form has been filled out with same findings: ☒

*Tick as applicable*

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1383004 JIV report S/N: 00876

25. Appendix 1: Overview sketch of the site

