IOINT INVESTIGATION REPORT FOR INCIDENT NO: 1340568 JIV report s/N: 0082	29
(Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties)	
A. GENERAL INFORMATION:	
1. Spill incident Number: 1340568 2. Type of incident* OTL SPILL	
3. Name of Location 28" Bomy - BENNY TRANS NIGGE PIRELIN	€
4. Name of nearest community 6000 WESTS. State: RIVERS 6. LGA (TOKANA	
7. Type of Production facility/Installation PIPELINE 8. Asset owner/District PIPELINE 7	COM!
B. INCIDENT INFORMATION:	
9. Details of incident a. Date of incident: 17th FEBRUNK 2015	
b. Start date/time of investigation: 22 ND FEBRUARY, 2015	
c. Investigation End date: 27TH FERNING, Return investigation duration, days: TIVE D4	<u>*</u> 7.
d. Description of spill point environment	
Firmed soil Decently excavated area	
☐ Under water ☐ Swampy ☐ Exposed pipe surface ☐ Well Platform (on Water) ☐ Drill Rig	
Additional observations around the spill point: THE ILLEGAL THEFT POINT WAS O TO BE NEW LEAKING WHEN THE ILLEGAL INSTALLED YATVE IS WHILE CRUDE BIL IMPART WAS SEEN WITHIN AND OUTS COFFERDAM DUE TO THIRN PARTY (BUNKERS) ARTILITIES	CLESCH INC THE
e. Description of leak point (tick as applicable);	
Drilled hole Hack saw cut Tear (),	
Complete Rupture	
☐ Failed Weld-on illegal hot tap valve, ☐ Failed Clamp ☐ Missing Pipeline/Flowline ☐ Crude oil theft (illegal bunkering) point, ☐ Third party tampering with Clam	·n
☐ Third party tampering with valve setting, ☐ Third party tampering with flang	-
☐Corrosión ☐Saver-pit over flow, ☐Surge vessel overflow,	~,
□ Bulging Outward □ Flare System/Bund wall failure □ Accidental 3 rd party e	quipment
impact	• •
Relief valve failure DOthers (specify)	
f. Incident caused by:	
☐ Third party interference (Sabotage☐; crude theft☐; Line theft☐; Accidental 3rd party damage☐)	
Operational Others (including Mystery spills)	•

^{*}This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire.

g. Spill point coordinates Massuring unit Massuring				CIDENT NO:	<u>34 a</u>	<u> </u>	JIV repor	t S/N:	0082
C. RISK ASSESSMENT 10. Type of environment: Land	g. Spill			M	MNA	W	10-A	تاء	
C. RISK ASSESSMENT 10. Type of environment: Land	 "								
C. RISK ASSESSMENT 10. Type of environment: Land			6391	56.13		٤	5324	83.2	2
10. Type of environment:	- -		1					<u> </u>	<u>-</u>
10. Type of environment:	ļ							 	
10. Type of environment:	L						<u>_</u>	<i>i</i>	
Land	C. RISK AS								
i. Type of environment to which oil has spread: Land	10.	Туре	of environment:						
Land		Land	Swamp	□Water	□Sea	isonal sw	amp 🗖 Sho	oreline/Wat	erfront
ii. Weather condition Rain Sunny Dry Wet Windy Hot Cool	i.	Туре о	f environment to	which oil has sp	read:				
Rain Sunny Dry Swet Windy Hot Cool		Land	☐ Swamp	□Water	□Riv	ver (ident	rify)		
11. Distance from the nearest sensitive habitat Government reserved and designated protected area Drinking water source Built up area Farmlands Fish Farm/Pond Fishing net Others (specify). 12. Containment measures put in place; Booms Trench Dyke Natural depression Others: 13. Any pictures or video coverage? 14. Further response/repair initiated as at the time of JIV? 15. Was there any disruption to the investigation? [Y] [N] 15. Was there any disruption to the investigation? [Y] [N]	ii.	Weath	er condition						
12. Containment measures put in place; Booms Trench Dyke Natural depression Pit Non Others: 13. Any pictures or video coverage? [Y] [N] 14. Further response/repair initiated as at the time of JIV? [Y] [N] 15. Was there any disruption to the investigation? [Y] [N]					□ Wet	□wi	indy	Hot	□cool
Booms Trench Dyke Natural depression Pit 13. Any pictures or video coverage? [Y] [N] 14. Further response/repair initiated as at the time of JIV? [Y] [N] If yes to item 14, give brief description: REPAIR WORK 15. Was there any disruption to the investigation? [Y] [N]	0 0 0	Drinking w Built up are Farmlands Fish Farm/ Fishing net	ater source ea Pond	esignated protec	ted area	[,m] ,m] ,m] ,m]	HONE WITH VICIN	SEEN IN 177
13. Any pictures or video coverage? 14. Further response/repair initiated as at the time of JIV? 15. Was there any disruption to the investigation? [Y] [N] [Y] [N]	12. Con	tainment m	easures put in pla	ace;					
14. Further response/repair initiated as at the time of JIV? [Y] [N] If yes to item 14, give brief description: REPAIR WORK 15. Was there any disruption to the investigation? [Y] [N]			Trench	□Dyke	□na	atural dep			□None
15. Was there any disruption to the investigation? [Y] [N]	13. Any	pictures or	video coverage?	•		[Y]	/[N]		
15. Was there any disruption to the investigation? [Y] [N]	14. Fu	rther respor	se/repair initiate	d as at the time	of JIV?	[Y].	/[N]		
15. Was there any disruption to the investigation? [Y] [N]	If yes to item	14, give brief	description: Q	EPAIR	ادلما	RK			
	<u> </u>	·			** TP				
If yes to item 15 give brief description:	15. Was	s there any	disruption to the	investigation?		[Y]	[N]	/	
3	If yes to item	ı 15 give br	ief description:						

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1340568 JIV report S/N: 00829

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

	I	6. Structures / Properties							
	S/N	Type of Structures	Description	Size	Number		Comme	ents	
	T	ONE W	(H7)	1	CA	OF	1	PACT	
	1	7. Crops/Economic Trees		<u> </u>			<u> </u>		
	S/N	Type of crops Young	·	Medium	Matured	Quanti	ty	Comments	}
	T	ONE M	MA	ARC	A OF	[1	XIP	RET	
	ı	8. Fish/Nets/Ponds		·		'	-		
	S/N	Fish/Nets/Ponds D	escription		Quantity/Size	Commen	ts		
		ONE /	HITHI	1	CA	OF	1×	PACT	
		9. Others (Specify) i.e. Ar							
	S/N	Others D	escription .	-	Quantity/Size	Comme	rts		
	M	ONE MI	THEX	1 A	REA	OF	1	MPACT	
TONAL	leak r	RAPHIC DESCRIPTION report, overview sketch of the WOF 28"	e site should be	added as an ap	uil report of the le opendix 1)	-		Contained in the	E A
	Bor	NEST SH	to w Inc	E CRUE	e oil Il	∟ <u>∈</u> G,•	€ Tt	HEFT POINT	
			· (5	S	LEAK C	2UE	A oī	231TIVITIES	
		THE THEFT		X ()a	OF THUR	is a	KTY	(ILLEGAL	
		AT CLOSED	()	لعج	BUNKE	25) F	Rom	THE MON	, -
		Position 15	NON		LEXKIN	G 4°	BAI	1 YALYE	
		LEAKING.)	FLAHGE 12° (Le				
28 TNP	$\langle \cdot \rangle$	·		, 		·	<u>-</u> .	725	۳3
, . <u></u>	V	Boni	1- BON	ry Page 3 of	LINE.			<i>₽ .</i> ★ T	ሢ የ

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1340568 JIV report \$/N: \$0829

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

	M N/NA /	10-BELT	
S/N	Northing NaTER	Easting M. ETER	
	63957.78	532481.8	4
	63957.55	532485.0	3
	63953.60	532484.4	-2
·	63957 · 55 63953 · 60 63954 · 05	532484.4 532480.9	2
			<u> </u>
ļ			
\vdash			
	<u> </u>		
	 		
	ļ <i>f</i>		
ļ			
/	1		
/			
L	· 	·	

ii Total Area of the pool of free phase oil in touch with soil

ESTIMATION OF OIL SPILL VOLUME FID =1340568 AT 26" BOMU BONNY TRANS INIGER PIPELINE AT BODO WEST JIV VOLUME CALCULATION REPORT OIL SPILLED ONSHORE/OFFSHORE (Leak stopped at source) Impacted Area Details 13.00 m² Total Calculated Area of Impact i Impact within SPDC R.O.W m² ii Impact outside SPDC R.O.W 1 Volume of oil recovered before completion of JIV (Vec.) i Estimated Recovered oil (Net) 2.00 bbls Estimated Recovered oil (Net) V_{rec.} 2.00 bbls 2 Computation of estimated residual volume on site Computation of volume of free phase oil (on land or confined water body) i Total area occupied by pool of free phase oil 10.00 m² ii Average depth of pool of free phase oil 0.010 iii Emulsification factor (If applicable, etse 0%) 30 % Estimated Volume of pool of free phase oil, Vpool 0.07 m° Estimated Volume of pool of free phase oil, Vpool 0.44 bbls Computation of estimated volume of infiltrated oil in the soil (V int) 1 Volume of infiltrated oil at spill point (V_{tota}) i Total area covered by the oil (infiltration) 3.00 m² 0.100 m ii Average depth of infiltration above leaking facility i.e. pipeline/flowline iii Soil type Sitty or sandy day iv P. (effective porosity of the soil) 12 % Third party Interference v Cause of spill Calculation of days for infiltration below the leaking point on pipeline or flowline Days on Site Incident Date JIV Date 2/22/2015 13:40 2/27/2015 14:45 If 'cause of spill' is operational, use 1 week as worst case 7 scenario except where 'days on site' exceeds 7. Infiltration of oil types in various soil types vs time. Soil type Approximate time to reach 1m depth below ground level Oil type Clay Sand Loam Bonny Medium 3 years > 10 years 3 weeks > 10 years Bonny Light 2 days 2 months viii Average depth of infiltration below leaking facility i.e. pipeline/flowline 0.001 0.101 m ix Total depth below ground surface of infiltration of oil 0.04 m³ Estimated Volume of infiltrated oil, V_{int a} Estimated Volume of inflitrated oil, V int a 0.23 bbls 2 Volume of infiltrated oil at second spill point [if applicable] (V_{intb}) m² i Total area covered by the oil (infiltration) ii Average depth of infiltration above leaking facility i.e. pipeline/flowline ш iii Soil type iv P. (effective porosity of the soil) 12 % 0.001 m v Average depth of infiltration below leaking facility i.e. pipeline/flowline 0.001 m vi Total depth below ground surface of infiltration of oil Estimated Volume of infiltrated oil, $V_{inf\,b}$ 0.00 m³ Estimated Volume of inflitrated oil, V inf b 0.00 bbls 3 Volume of infiltrated oil outside immediate spill point(s) region (V_{infe}) i Total Area covered by the oil (infiltration) m²

Soil type				Silty or sandy clay
P _e (effective porosity of the	soil)			12 %
Average depth below grou	0.001 m			
Estimated Volume of Infl	Itrated oil, V _{kel c}			0.00 m ³
Estimated Volume of Infl	Itrated oil, V _{inte}	· · · · · · · · · · · · · · · · · · ·		0.00 bbis
Volume of infiltrated oil o	outside Immediate spill point(s) regio	on (tuperficial image	• 1/2 - 1	
Total Area covered by the		ou (suberrada mithac	S V inf d)	m²
Total Area of the pool of fro	ee phase oil in touch with soil			m²
Average depth below grou	nd surface of infiltration of oil			0.001 m
Estimated Volume of infi	Protect oil V		•	3
Estimated Volume of Infil	trated oil. V	 -		0.00 m ³
				0.00 0018
Estimated Total Volume	of infiltrated oil, V _{inf}		_	0.04 m ³
Estimated Total Volume	of Inflitrated oil, V _{inf}			0.23 bbls
O	.e			
	rf oll on open water based on standa 	ard coloration		
Total area of oil on open w Table of average death of a	ater oil on water based on coloration			m ²
		Link to Coverage Visual		
Spill Factors from USCG FOG	(2000 Edition)	Aid Percentage coverage		
	Thickness (mm)	(%)	Votume (m3)	
Barely Visible	0.00004		0.0000	
Silvery			0,0000	
Slight Color Bright Color	0.00015		0.0000	
Dull	0.0003		0,0000	
Dark	0.002		0.0000	
Black oil	0.1		0.0000	
Emulsion (30% Oil)	1		0.0000	
	Percent Total:	0%	0.0000	
Estimated Volume of oil of		<u>_</u> .		0.00 m ³
Estimated Volume of oil o	on open water, v _{wat}			0.00 bbls
iation of evaporated volu				
TRUDIT OF EVAPORATE VOIC	iiii o			
	Evaporation Factors (E-Factor) for S	PDC Crude oil	<u>-</u> .	
Residence time	of spilled oil (days on site)	Oil ty		
		Bonny Light	Bonny Medium	
	< 1 day	10%	5%	
	1-7 days	25%	15%	
	> 7 days	40%	25%	
Nas oil recovery before JII	/ completion done before JIV date?		ļ	#o ▼
Estimated volume available	2.67 bbis			
E-factor				
stimated Volume of eva	porated oil. V		<u> </u>	6.47 bbls
			······································	U.47 UUS
et Total Estimated	Spilled Volume, V.			2 44 bbla
Net Total Estimated				3.14 bbls

IT INVESTIGATION R	EPORT FOR INCIDENT NO: 1340568 JIV report S/N	00829
G. INCIDENT INFOR		
20. Impacted Area	Details	
	calculated area of impact 0.0013 #4	
_		
•	t outside SPDC R.O.W	
21. <u>volume of oil r</u>	Recovered oil V _{reci} :	Barrels
		Dattels
Comoned recove	ery/evacuation from source with no impact to environment: Barrels	
22. Net Estimated	Spilled Volume V _{Est} (bbls)* =	
•	3.14 BARREIS	
Estimated Reported V	olume** V _{rep} (bbls)= 4 BARKE(S.	
 Reported spilled ve 	was done using an excel based tool.(see attached for details on the calculation) plume is an estimate es taken into consideration for estimating the spilled in the hox below:	
<u> </u>		
Conversion of m' to barrels is	estimated volume is to be done on site as far as practicable using the new spill volume est s Volume (m3) x 6.29; **Round up estimated volume to next whole number using the follow excess of I bbl is rounded up to the next whole number.	
Any spill volume in	n less than 1 bbl is rounded up to the next 0.1 bbl.	
1	Calculated volume = 15.3 bbl Reported volume = 16 bbl Calculated volume = 0.35 bbl Reported volume = 0.4 bbl Calculated volume = 0.01 bbl Reported volume = 0.1 bbl.	

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1340568 JIV report \$/N: 00829

23. GENERAL STATUS OF THE SITE

A. Joint investigation of the incident site found that there is no residual in response and JIT therefore recommend that the site be closed out	pact after the initial
B. Investigation of the incident site showed that there is residual impact on works	site requiring further

24. REPRESENTATIVES

This report was filled, agreed and signed by the	e following joint investig	gation representatives:
Host Community:		

- National Oil Spill Detection and Response Agency [NOSDRA]:
- State Ministry of Environment [SME]:
- Nigeria Police Force [NPF]:
- Shell Petroleum Development Company [SPDC]:

Department of Petroleum Resources [DPR]:

- Signatories agree with reported findings:
- Separate DPR form has been filled out with same findings□

Tick as applicable

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 134 05 68 JIV report \$/N: 00829

25. Appendix 1: Overview sketch of the site

