JOINT INVESTIGATION REPORT FOR IN	ICIDENT NO: 132	0947 JIV report S/N:	00823
(Note: As practicable as possible the JIT	report is to be signed in	the field by all the participativ	ng parties)
A. GENERAL INFORMATION:			
1. Spill incident Number: 13209	<u>147</u> 2.7	ype of incident* OIL S	PILL
3. Name of Location 30" N	EMBE CR	EEK PIPELIN	<u>IE</u>
4. Name of nearest community OPON	AAKIRI_5. State:	RIVERS 6. LGA DE	GEMA
7. Type of Production facility/Installation	OIL PIPELIN	B. Asset owner/District P1	PELINE
B. INCIDENT INFORMATION:			
9. Details of incident a. Date of incident: 18 T H	JANUAR'	Y, 2015	
b. Start date/time of investigation:	26TH JA	NUARY, 2015/1	3\34Hours
c. Investigation End date: 2617	JANUARY 015 Actual	investigation duration, days:_	ONE(I) DAY
d. Description of spill point enviro	nment		
☐Firmed soil	Loose soil	Recently excavated	area
☐ Under water	Swampy	DExposed pipe surfac	e
☐Well Platform (on Water)	•	☐Drill Rig	
Additional observations around the sinvestication Team AROUND THE SPILL PIEAM ON BEHALF OTHE TOINT INVESTIGATION THE SPILL POINT BY e. Description of leak point (tick a Drilled hole Complete Rupture Failed Weld-on illegal hot tap vortice oil theft (illegal bunke Third party tampering with vortice of the property tampering with	OINT BY THE F THE SPOC ATION VISIT. NAL AREA) WHUNKNOWN PERSON. Hack saw cut Inward dent, alve, Failed Clampering) point, valve setting, Saver-pit over flustrate System/But System/But System/But Spock.	RESIDENT PIPEL ASSET OWNER, PR ALSO, A STEEL (ICH HAD BEEN INS ICH HAD BE	INE MAINTENANCE EPARATORY TO ASING (WITH TALLED AROUND CED, IMPACTED BROWN SILTY CLAY WITH ORGANIC MATTER. Dowline ong with Clamp ong with Clamp ong with flange, ow,
f. Incident caused by:	,		
Third party interference (Sabota	ge□; crude theft [/]; Lir s (including Mystery sni		damage□)

^{*}This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire,

	RT FOR INCIDENT NO: 1320	947_JIV report S/N:	00823
g. Spill point coordinate Measuring unit		(Mro-Bei)	
Northing:		Easting:	
	63637-68	507381.0	<u> </u>
		 	
<u></u>			
C. RISK ASSESSMENT 10. Type of en	······································		
		_	
🗖 Land 🕡	Swamp 🗆 Water 🗀 S	easonal swamp Shoreline/Waterfi	ront
i. Type of envi	ronment to which oil has spread:		
□Land ✓	Swamp 🗹 Water 🗀 🖺	River (identify)	
ii. Weather con	dition		
□Rain Z S	unny Dry DWet	□Windy □Hot □	
11. Distance from the nea	•		40001
 Drinking water see Built up area Farmlands Fish Farm/Pond Fishing net 	rved and designated protected area ource MANGROVE VEGETATI	[,m]	Y SPILL.
12. Containment measure	s put in place;		
,	French DDyke DN ERDAM CONSTRUCT	latural depression Pit ED AROUND: SPILL Po	□None iNT.
13. Any pictures or video		[Y V [N]	
14. Further response/rep	air initiated as at the time of JIV?	[X] [N]	
If yes to item 14, give brief descriped to the series of t	FREE PHACE OIL \	NITHIN COFFERDAM	<u>Construct</u>
AROUND SPILL PO	INT WAS DONE.		
15. Was there any disrupt	ion to the investigation?	[Y] [N]	
If yes to item 15 give brief des	APPLICA	BLE	

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 13 20947 JIV report S/N: 00823

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

16. Structures / Properties

S/N Type of Structures	Description	Size	Number	Comments
tone su	7	100		10
INO INF M	THIN	AKE	A OF	MPACT -

17. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
	MANGRAVE		<u> </u>	/	WITHIN AN	WITHIN
<u> </u>	VEGETATION				AREA OF	Shi-
		<u></u>			0.38 Ha.	IMPACTED
L			<u> </u>			REGION.


18. Fish/Nets/Ponds

S/N	Fish/Nets/Ponds	Description		Quantit	y/Size	Com	ments	
X	ONE	WITHIN	AR	EΑ	0	F	IMPACT	
				1			•	

19. Others (Specify) i.e. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
N	ONE	MITHIN A	REA	OF IMPACT

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detail report of the leak point should be contained in the



JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1320947 JIV report S/N: 00823

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION 20. Impacted area boundary Coordinates (If more, Print and attach as an appendix)

S/N	Northing	Easting
		X (C
	a	+ 8
		UZ,
		6
		· L
-		
	_	
) X *
	10	`
	*	
	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	/ /
		M MS
	7/	a Marian
	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	() (
	11, 62	
	// X5	
	10.7	
	V)	
	·	
		-
	<u> </u>	

APPENDIX A

IMPACTED AREA COORDINATES (MINNA MID-BELT)

30" NEMBE CREEK PIPELINE AT OPOMAKIRI (INCIDENT NO. 1320947).

30. NEWR	CKEEK PIP	ELINE AT OF
Point	x	У
34	507410.68	63639.46
35	507265.08	63894.12
36	507198.53	63909.00
37	507181.98	63958.80
38	507078.38	63947.95
39	507000.71	63951.80
40	506900.70	63955.81
41	506730.29	63884.42
42	506704.29	63720.17
43	506752.02	63543.13
44	506711.13	63447.37
45	506746.02	63327.49
46	506869.79	63251.66
47	506878.90	63185.29
48	506728.73	63014.19
49	506672.98	62888.97
50	506742.95	62732.15
51	506504.39	62752.92
52	506452.50	62705.10
53	506494.94	62657.09
54	506598.37	62584.99
55	506614.93	62542.57
56	506677.58	62533.99
57	506694.52	62589.02
58	506781.67	
	506835.51	62673.09
59		62770.67
60	506743.15	62829.84
61	506717.31	62859.38
62	506704.46	62905.49
63		
64	507188.57	63933.58
66	506786.73	63336.62
67	506740.61	63393.86
68	506777.81	63495.15
69	506772.43	63574.42
70	506745.32	63697.10
71	506730.50	63808.22
72	506761.93	63865.67
73	506809.68	63885.96
74	506902.61	63918.83
75	507020.48	63913.00
76	507056.15	63927.73
77	507133.78	63905.45
78	507381.08	63637.68
79	507369.94	63614.55
80	506701.71	63848.44

81	506763.10	63506.60
82	506731.35	63480.14
. 83	506713.35	63384.89
84	506789.55	63292.81
85	506672.08	62912.87
86	506709.33	62820.80
87	506752.72	62763.64
88	506714.62	62660.99
89	506670.17	62634.53
90	506625.72	62626.06
91	506598.21	62632.41
92	506550.58	62705.45
93	506756.96	62980.60
94	506894.54	63124.54
95	506941.11	63210.26
96	506930.52	63252.60
97	506894.54	63285.40
98	506752.72	63457.91
99	506791.88	63532.00
100	506737.91	63841.03
101	506949.57	63924.64

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1320947 JIV report S/N: 00823

U.	INCI	มผมเ	,	II Y I'	v	KJ	V 1 P	7.1	I,	O)	,

20. Impacted Area Details

	Total calculated area of impa	$\frac{1}{1}$	7H9	
•	Impact within SPDC R.O.W	フェ ィ		
•	Impact outside SPDC R.O.W	V=C		
21. Volume	of oil recovered before com	pletion of JIV (Vrect):		
	c I	Recovered oil V _{reel} :	25.16	Barrels
Controlled	d recovery/evacuation from s	source with no impact	t to environment:	<u> </u>

22. Net Estimated Spilled Volume V _{Est} (bbls)* = 216.2	
Estimated Reported Volume** V _{res} (bbis)=	217 BARRELS	

*Notes:

Volume estimation was done using an excel based tool (see attached for details on the calculation)

Reported spilled volume is an estimate

Write other relevant notes taken into consideration for estimating the spilled in the box below:

NOT

APPLICABLE

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of m³ to barrels is Volume (m3) x 6.29; **Round up estimated volume to next whole number using the following rules:

Any spill volume in excess of -1 bbl - is rounded up to the next whole number.

Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

ESTIMATION OF OIL SPILL VOLUME

IL SPILLED ONSHORE	OFFSHORE (Leak stopped at	source)		
npacted Area Details				
Total Calculated Area of	Impact			119,850.00 m ²
i Impact within SPDC R.O.	v			m²
ii Impact outside SPDC R.C	.W			m²
F				
olume of oil recovered befor	e completion of JIV (V)			
i Estimated Recovered oil (25.16 bbls
				25:20,000
Estimated Recovered of	(Net) V _{rec.i}			25.16 bbls
				-
omputation of estimated res	idual volume on site			
· · · · · · · · · · · · · · · · · · ·	of free phase oil (on land or confined	f water hodul		
i Total area occupied by po	· ·	a Mater Body/		5,096.00 m ²
ii Average depth of pool of f	*			0.002 m
	(If applicable, else 0%) ^			<u> </u>
in Citabilicador lacio	(ii applicable, else 070)			
Estimated Volume of po	d of from shape off V			10.19 m³
				
Estimated Volume of po	or free phase oil, v _{pool}	·		64.11 bbis
iii <u>Soil type</u> iv P _e (effective porosity of the	n above leaking facility i.e. pipeline/flow e soil)	eria ng		1.800 m Sitty or sandy day 12 %
v Cause of spill				Third party interference:
	7.60.41. 4. 4. 4. 4. 4.		I	
	infiltration below the leaking point on p			
Incident Date	JIV Date	Days on Site		
1/18/2015 13:19	1/26/2015 17:10	8		
	ational, use 1 week as worst case here 'days on site' exceeds 7.	7		
SCOTIGINO BACEBULY	Here days on sile exceeds /.	· <u> </u>	ļ	
·	Inflitration of oil types in various soil (types vs time		7
Soil type	Approximate time to reach	•	nd level	7
Oil type	Sand	Loam	Clay	7
Bonny Medium	3 weeks	3 years	> 10 years	1
Banny Light	2 days	2 months	> 10 years	1
Dunny Light	2 44/3	2 11011030	> 10 years	_
i Oil type				Bonny Light
	n below leaking facility i.e. pipeline/flow	dina		0.002 m
	, color realisting learney lie. pipesities for	· · · · · · · · · · · · · · · · · · ·		0.002
x Total depth below ground	surface of infiltration of oil			1.802 m
* Total achai pelati Albana	School of Shind adolf of Oil			1.802 117
Entirented Matures of Ind	Manada at a 25 a 5			
Estimated Volume of Infi				0.22 m³
Estimated Volume of infi	trated oil, V inta			1.36 bbls
	t second spill point (if applicable) (\	(of b)		2
i Total area covered by the	,	. T		m ²
	above leaking facility i.e. pipeline/flov	viine		<u> m</u>
ill <u>Soil type</u> in P. (effective porcelly of the	eoil\			- Select -
P, (effective porosity of the	SUIT			0 %
 Average depth of infiltratio 	r below lesking facility i e. pineline/flow	dine		0.000 m
	recon leaking lacking i.e. pipelinerion			
	• • • • •			
vi Total depth below ground	surface of infiltration of oil			0.000 m
•	surface of infiltration of oil			
Estimated Volume of Infi	surface of infiltration of oil			0.000 m

JOINT INVESTIGATION REPORT SPILL VOLUME ESTIMATE FOR INCIDENT NO: 1320947

	outside immediate spill point(s) regio	on (V _{infe})		
Total Area covered by the	• • • •			17,278.00 m ²
•	ee phase oil in touch with soil			26.00 m*
Soil type				Slity or sandy clay
P _e (effective porosity of the	: SON)			12 %
Average depth below ground surface of infiltration of oil			0.002 m	
Estimated Volume of Infi	Itrated oil, V _{inf c}			4.55 m ³
Estimated Volume of infi	ttrated oil, V _{iol.c.}			28.63 bbls
Total Area covered by the	outside immediate spill point(s) regio oil (inflitration) ee phase oil in touch with soil	on (superficial impact	t, V _{ista})	3,800.00 m² m²
Average depth below grou	nd surface of infiltration of oil			0.002 m
Estimated Volume of infl	Itrated oil, V _{lofd}			0.67 m³
Estimated Volume of Infl	Itrated oil, V _{brf d}			4.19 bble
Estimated Total Volume				5.43 m ³
Estimated Total Volume	of Inflitrated oil, V _{inf}			34.18 bbls
Spill Factors from USCG FOG	oil on water based on coloration	Link to Coverage Visual Aid		•
	Thickness (mm)	Percentage coverage (%)	Volume (m3)	
Barely Visible	0.00004		0.0000	
Silvery	0.00008		0.0000	
Slight Color	0.00015	30%	0.0042	
<u>Bright Color</u>	0.0003		0.0000	
<u>Duft</u>	0.001	60%	0.0562	
<u>Dark</u>	0.002		0.0000	
Black oil	0.1	10%	0.9388	
Emulsion (30% Qil)	1 Percent Total:		0.0000	
	Percent roun:	100%	0.9972	
Estimated Volume of oil	on open water V			1.00 m³
Estimated Volume of oil				6.27 bbls
ulation of evaporated volu	ume Evaporation Factors (E-Factor) for S			
		Oil ty	pe Bonny Medium	
	Evaporation Factors (E-Factor) for S of spilled oil (days on site)	Oil ty Bonny Light 10%	Bonny Medium 5%	
	Evaporation Factors (E-Factor) for S of spilled oil (days on site) <1 day 1-7 days	Oil ty Bonny Light 10% 25%	Bonny Medium 5% 15%	
	Evaporation Factors (E-Factor) for S of spilled oil (days on site)	Oil ty Bonny Light 10%	Bonny Medium 5%	
Residence time	Evaporation Factors (E-Factor) for S of spilled oil (days on site) < 1 days 1-7 days > 7 days Vicompletion done before JiV date?	Oil ty Bonny Light 10% 25%	Bonny Medium 5% 15%	No ▼ 129.72 bbis
Residence time	Evaporation Factors (E-Factor) for S of spilled oil (days on site) < 1 days 1-7 days > 7 days Vicompletion done before JiV date?	Oil ty Bonny Light 10% 25%	Bonny Medium 5% 15%	
Residence time Residence time Was oil recovery before Ji' Estimated volume available	Evaporation Factors (E-Factor) for S e of spilled oil (days on site) < 1 day 1-7 days > 7 days Vicompletion done before JIV date? e for evaporation	Oil ty Bonny Light 10% 25%	Bonny Medium 5% 15%	129.72 bbis

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1320947 JIV report S/N: 00823

23. GENERAL STATUS OF THE SITE

A. Joint investigation of the incident site found that there is no residual impact after the response and JIT therefore recommend that the site be closed out	ne initial
B. Investigation of the incident site showed that there is residual impact on site requiring works	g further

24. REPRESENTATIVES

This re	port was filled, agreed and signed by the following joint investigation representatives:
•	Host Community:
•	Department of Petroleum Resources [DPR]: 3
	National Oil Spill Detection and Response Agency [NOSDRA]:
_	The state of the s
	State Ministry of Environment [SME]: 5
•	State Willistry of Environment [SWID].
	Nigeria Police Force [NPF]:
•	Augeria Ponce Porce (APP).
	Shell Petroleum Development Company [SPDC]:
•	Shell Petroleum Development Company [SPDC]:
•	Signatories agree with reported findings:
	_/
•	Separate DPR form has been filled out with same findings
Ì	•
	Tick as applicable
!	

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1320947 JIV report S/N: 00823

25. Appendix 1: Overview sketch of the site

