111E 011622 1 21110 220 111		_	0.304
IOINT INVESTIGATION REPORT FOR INC	(IDENT NO: <u>13245</u>	19 JIV report S/N: 0	0824
(Note: As practicable as possible the JIT re	port is to be signed in the fi	eld by all the participating po	urties)
A. GENERAL INFORMATION:			1
1. Spill incident Number: 13245	2.Type of	fincident* OIL SPI	LL/FIRE
3. Name of Location CAWTH	ORNE CHA	NNEL I WE	119
4. Name of nearest community <u>CAPTA</u>	IN KIRIS. State: RIV	ERS 6. LGA DEG	EMA
7. Type of Production facility/Installation	WELL HEAD 8. A.	set owner/DistrictSW	AMP I
B. INCIDENT INFORMATION:			
9. Details of incident a. Date of incident: 25TH	JANUARY,	2015	
b. Start date/time of investigation:	28TH JANI	JARY, 2015/1 tigation duration, days: 01	2:25Hours NE (1) DAY
	, -		,
d. Description of spill point environ	·	□ n a 4.1	_
☐Firmed soil	Loose soil	Recently excavated area	ı
Under water	☐ Swampy	Exposed pipe surface	
Additional observations around the sp	•	☐Drill Rig	
OF AN UNKNOWN THE CONFISCATED BY SECUTE PRIOR TO JIV DATE AS AT TIME OF INCIDEN CONFIRMED TO BE NON- e. Description of leak point (tick as Drilled hole	TREPORT, ON CLOS	BSERVED BY THE VICE OBSERVATION	NELL 4 SLOT OF WELL 9 ST PRODUCED IN
Complete Rupture	☐Inward dent,	☐Well head tampering ⁴	THAT OCCURRED ON
Failed Weld-on illegal hot tap ve		☐Missing Pipeline/Flow	INCIDENT DATE BUT
Crude oil theft (illegal bunke		Third party tampering	with ClampPRIOR TO JIY
☐ Third party tampering with v	alve setting,	☐ Third party tampering	with flange OIL STAINS
Corrosión	Saver-pit over flow,	manife resser overnow,	WERE NOTICES WITHIN THE POSTTION
☐Bulging Outward	☐Flare System/Bund v	vall failure LAccidental 3'	^u party equipment ⊘≥
impact	ure Cor	n unit failure 🔲 Cold	Vent THE BEAN BOX
Relief valve failure	Others (specify)	AN BOX CAP Y UNK NOWN	WHICH HAD BEEN REMOVED
f. Incident caused by:	PERCE) NGS).	AND RE-FABRICATED
Third party interference (Sabota	geta; crude theft(a); Line the	eft⊡; Accidental 3" party da BY THE A S	SET OWNER) BY
☐Operational ☐Others	(including Mystery spills)_	BY THE AS	PERSON(S). SOME
		DESERVED AN	EMS LEFT (AND
*This can be: a) Oil Spill b) Drilling	incipi	ENT) BY UNKHOWN	L PERSONIS BUT
*This can be: a) Oil Spill b) Drilling. THE ASSET OWNER	fluid/Chemical c) siliation u) ci	EROM SITE (To DA	EVENT ENTER BY
USAGE OR REMOVAL	BY SUSPECTED (Rube oil Thieves)	WERE DISPLAYED
AT THE ASSET OWN	ER'S DEELE AND	COMPRISED A P	EN KNIFE, BURNT
USAGE OR REMOVAL AT THE ASSET OWN HOSE, LIFTING BELT,	STEEL HAMMER,	RE-FABRICATED B	EAN BOX COVER OR
CAP WITH CRUDE THEFT ROPE SUIL IMPACTED ON	COMMERTIONS, N	INVER CIRCLE MAN	N II DRIVING TALLING

4

		EPORT FOR IN	CIDENT NO:	1324	519	JIV repo	rt S/N:	0082
g. Sp	Measuring:		rv ₎ ,	nna	Mid Easting:	bel	 	
	Tvortining.	·					_	
	€	<u>,0485.</u>	93		50	837	19.40	· · · · · · · · · · · · · · · · · · ·
			10	71				70.
				-				
C. RISK	ASSESSME	NT .						
10.	Туре	of environment:						
	Land	□Swamp	Water	□Se	asonal swai	mp []Sh	oreline/Wat	erfront
	i. Type	of environment to	which oil has s	pread:				
	Land	 	Water	□Ri	ver (identif	y)		
	ii. Weath	er condition						
	Rain stance from	Sunny the nearest sensiti	□Dry ve habitat	□Wet	□Wind	dy	□Hot	□cool
	Drinking v Built up ar Farmlands Fish Farm Fishing ne	ea Pond	-]]] [] N	,m] ,m] ,m] ,m] ,m] ,m]	PA CTED	BY SPILL.
12. Co	ontainment m	easures put in pla	ice;					
_	Booms Others:	Trench	Dyke	□na	itural depre	ssion	□Pit	None
13. At	ny pictures or	video coverage?			[X] /	[N]		
14. F	urther respon	se/repair initiated	as at the time of	of JIV?	[Y]	[N]	•	
lf yes to item	14, give brief	description:				•		
	กโ	A	PITC	ARI	F.			
15 37				·	(/ (/		_ .	
	-	disruption to the i	nvestigation?		[Y]	[N]		
If yes to ite	m 15 give br	ief description:	A					
	NO	I = I	446[101	4 R L	田		

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1324519 JIV report S/N: 00824

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

16. Structures / Properties

S/N Type of Structures	Description	Size	Number	Comments
Marin VI	l . 	A		
1111)NE W	/ 	H A	IFA OF	HMPA CT
				######################################


17. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
_1 _	MANGROVI		/		WITHIN AN	IMPACTEN
<u></u>	VEGETATION	L			IMPACTED	
ļ				<u> </u>	AREA OF	
					7.33Ha.	

18. Fish/Nets/Ponds

S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
N	ONE V	17 1 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	CEA (OF IMPACT

19. Others (Specify) i.e. Animal Traps



JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1324519 JIV report S/N: 00824

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION 20. Impacted area boundary Coordinates (It more, Print and attaches an appendix)—

	. Impacted area boundary Coordinates (1) ma	INA" "MITO" BELT
S/N	Northing (M)	Easting (M)
	60321.97	508207.25
	60346.56	508 201.13
	60358.88	508185.75
	60536.75	508330.99
	60683.98	508442.28
	60733 · 07	508473 . 21
	60435.19	508423.28
	60444.71	508275.32
	60300.48	508201 . 04
	60254.31	508244 . 11
,	60201.96	508 308 . 74
	60167.37	508409.03
	60122:11	508 299 . 33
	60134.46	508268.52
- 	60162.21	508216.17
	60263.82	508 102 . 32
	60330.35	508068.25
	60802.63	508 536 · 83
	60784.11	508647.95
	60735.96	508749.82
	60628.54	508681.29
	60541.49	508 610 . 91
	60439.63	508 610 · 91 508 542 · 38 508 375 · 69
 	60321.09	508375.69
		Des /

O. Impacted Area Details	OIL STAIRS ON WA	uv = 7.33 HA $ver = 4.73 HA$ $ver = 2.93 HA$
Impact within SPDC R.O.V		
Impact outside SPDC R.O.	1.Cc	
Volume of oil recovered before con		
^	Recovered oil V _{recJ} :	Barrels
Controlled recovery/evacuation from	source with no impact to env	ronment:
NIL	Barrels	
5 Mid Futherstad Cailled Values V	(bble)* = f	
2. Net Estimated Spilled Volume V	$E_{\text{H}}(\text{BDIS})^{*} = (9.29)$	
	0,~,	
imated Reported Volume** V _{ren} (bbls)=	70 BARRE	

IN CONSIDERATION OF THE FIRE INCIDENT ACCOMPANYING THE SPILL, THE NET ESTIMATED SPILLED VOLUME (IN TOTAL) IS INCLUSIVE OF THE ESTIMATED SPILLED VOLUME CONSUMED BY FIRE, AS EXPLAINED IN THE ATTACHED SPILLED VOLUME ESTIMATION DETAILS.

Calculation of the respective estimated valume is to be done on site as far as practicable using the new spill valume estimation software on site; Conversion of m^3 to barrels is Volume (m3) x 6.29; **Round up estimated valume to next whole number using the following rules:

Any spill volume in excess of 1 bbl is rounded up to the next whole number.

Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for volumn estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

ESTIMATION OF OIL SPILL VOLUME

OIL SPILLED ONSHORE	E/OFFSHORE (Leak stopped a	t source)		
impacted Area Details				
Total Calculated Area o	f impact			149,900.00 m ²
i Impact within SPDC R.O.	W			m²
il Impact outside SPDC R.(D.W			m²
•				
Yolume of oil recovered before	re completion of J(V (V)			
i Estimated Recovered oil				bbls
	V7			
Estimated Recovered of	I (Net) V _{rec.}			0.00 bbis
				
Computation of estimated re	sidual volume on site			
	of free phase oil (on land or confine	d water backs		
i Total area occupied by po	-	o water body,		3,200.00 m ²
ii Average depth of pool of	•			
iii Emulsification factor	•			0.002 m
III Emulsincation factor	(if applicable, else 0%)			70]%
	-1 -6 f111 14			
	ol of free phase oil, V _{pool}			1.92 m³
Estimated Volume of po	ol of free phase oil, V _{pool}			12.08 bbls
i Total area covered by the ii Average depth of infiltration iii <u>Soil type</u> iv P _a (effective porosity of the	on above leaking facility i.e. pipeline/flo	wline		m ² m Silty or sandy clay
v Cause of spill				Third party interference
	··			
vi Calculation of days fo	r infiltration below the leaking point on	pipeline or flowline	!	
Incident Date	JIV Date	Days on Site		
1/25/2015 3:20	1/28/2015 12:45	3		
	rational, use 1 week as worst case	,		
scenano except	vhere 'days on site' exceeds 7.	7	J	
	Infiltration of oil types in various sail	tynas ve tima		7
Soil type	Approximate time to read		nd level	╡
Oil type	Sand	, 		┥
		Loam	Clay	
Bonny Medium	3 weeks	3 years	> 10 years	
Bonny Light	2 days	2 months	> 10 years	J
uit Oil tono				Г енте
vii Oil type	an halou tagkina facility i a singling like	41		Bonny Light.
VIII Average depth of innitration	on below leaking facility i.e. pipeline/flow	WILLE		0.001 m
ix Total depth below ground	surface of infiltration of oil			0.001 m
Estimated Volume of im				0.00 m ³
Estimated Volume of im	iltrated oil, V _{inf a}			0.00 bbls
2 Volume of infiltrated oil	at second spiil point [if applicable] (V _{int b})		
i Total area covered by the				m²
ii Average depth of infiltration	on above leaking facility i.e. pipeline/flo	viine		
iii <u>Soil type</u>				- Select - Ψ
iv P _n (effective porosity of the	e soil)			0 %
v Average depth of infiltration	on below leaking facility i.e. pipeline/flow	vline		0.000 m
vi Total depth below ground	surface of infiltration of oil			0.000 m
Estimated Volume of Im	litrated olf, V _{inf b}			0.00 m³
Estimated Volume of in				0.00 bble

JOINT INVESTIGATION REPORT SPILL VOLUME ESTIMATE FOR INCIDENT NO: 1324514

Total Area covered by the Total Area of the pool of fro	oil (infiltration) ee phase oil in touch with soil			19,500.00 m² m²
Soil type				Silty or sandy day ▼
P _a (effective porosity of the	soit)			12 %
Average depth below groun	nd surface of infiltration of oil			0.001 m
Estimated Volume of infi	itrated oil. V _{infe}			1.92 m³
Estimated Volume of infi				12.10 bbls
	· • • • • • • • • • • • • • • • • • • •			·
	outside immediate spill point(s) regio	on (superficial impact	l, V _{Inf d})	2
Total Area covered by the	•			50,600.00 m ²
Total Area of the pool of fre	se phase oil in touch with soil			m²
Average depth below groun	nd surface of infiltration of oil			0.001 m
Estimated Volume of infil	itrated oil, V _{inf d}			3.33 m³
Estimated Volume of Infl	trated oil, V _{inf d}			20.93 bbls
5-2-4-1 Total Valuese	-#(-#Historian all 13			- n=3
Estimated Total Volume (Estimated Total Volume (5.25 m ³
CHUMENTA IVIEN FURNIS	A Illinated on, 4 M			33.03 bbls
Total area of oil on open w Table of average depth of	oil on water based on coloration	Link to Coverage Visual	ı	76,600.00 m²
Spill Factors from USCG FOG	(2000 Edition)	Ald		ı
ļ	Thickness (mm)	Percentage coverage (%)	Volume (m3)	
Barely Visible	0.00004	80%	0.0025	
Silvery	0.00008		0.0000	
Slight Color	0.00015		0.0000	
Bright Color	0.0003	15%	0.0034	
<u>Dult</u>	0.001		0.0000	
<u>Dark</u>	0.002	5%	0.0077	
Black oil	0.1		0.0000	
Emulsion (30% Oil)	Percent Total:	4000	0.0000	
	1 TITTIN	100%]	0.0136	
Estimated Volume of oil	on open water, V _{wat}			0.01 m ³
Estimated Volume of oil o				0.09 bbis
uiation of evaporated volu	ime			
	Evaporation Factors (E-Factor) for S	PORC Crude Ail		<u> </u>
		Oil ty	De.	
Kësidence time	of spilled oil (days on site)	Bonny Light	Bonny Medium	
	< 1 day	10%	5%	
	1-7 days	25%	15%	
		40%	25%	
<u>. </u>	> 7 days	7070		'
Was oil recovery before JII	> 7 days V completion done before JIV date?	4070		
Was oil recovery before JH Estimated volume available	V completion done before JIV date?	7070		No ▼
Estimated volume available	V completion done before JIV date?	40%		45.19 bbls
•	V completion done before JIV date?	-1070	1	

NOTE: The spill incident was accompanied by a fire incident, hence an estimate (taken as 20% of the computed spilled volume available for evaporation) is hereby made for the spilled volume consumed by fire. Thus, 20% x 45.19 = 9.04 barrels. Therefore, the total spilled volume (including that burnt by fire) = net estimated spilled volume (without fire) + estimated spilled volume consumed by fire = 60.25 + 9.04 = 69.29 barrels.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1324-519 JIV report S/N: 00824

23. GENERAL STATUS OF THE SITE

A. Joint investigation of the incident site found that there is no residual impact after the initial
response and JIT therefore recommend that the site be closed out
B. Investigation of the incident site showed that there is residual impact on site requiring further
works D
•

24. REPRESENTATIVES

his re	eport was filled, agreed and signed by the following joint investigation representatives:
•	Host Community:
•	Department of Petroleum Resources [DPR]:
•	National Oil Spill Detection and Response Agency [NOSDRA]:
•	State Ministry of Environment [SME]:
•	Nigeria Police Force [NPF]: □
•	Shell Petroleum Development Company [SPDC]:
•	Signatories agree with reported findings:
•	Separate DPR form has been filled out with same findings
	Tick as appli

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1324519 JIV report S/N: 00824

25. Appendix 1: Overview sketch of the site

