

JOINT INVESTIGATION REPORT

INCIDENT NO: 1796265 JIV report S/N: No 000291

(Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties)

A. GENERAL INFORMATION:

1. Spill incident Number: 1796265 2. Type of incident* OIL SPILL
3. Name of Location 12" IMORIVER - OGALE PIPELINE
4. Name of nearest community UMUDLADO 5. State: ABIA 6. LGA UKWA WEST
7. Type of Production facility/Installation OIL PIPELINE
8. Asset owner/District THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LTD (SPDC)

B. INCIDENT INFORMATION:

9. Details of incident
a. Date of incident: 2ND FEBRUARY 2017
b. Start date/time of investigation: 4TH JUNE 2017/1100HRS
c. Investigation End date: 4TH JUNE 2017 Actual investigation duration, days: ONE (1) DAY
d. Description of spill point environment

- | | | |
|--|--|---|
| <input type="checkbox"/> Firm soil | <input checked="" type="checkbox"/> Loose soil | <input checked="" type="checkbox"/> Recently excavated area |
| <input type="checkbox"/> Under water | <input type="checkbox"/> Swampy | <input type="checkbox"/> Exposed pipe surface |
| <input type="checkbox"/> Well Platform (on Water | <input type="checkbox"/> DrillRig | |

Additional observations around the spill point: THE JOINT INVESTIGATION TEAM SAW A CRUDE OIL THEFT POINT INSTALLED AT 12 O'CLOCK POSITION. THE CRUDE THEFT POINT WAS CONFIRMED LEAKING AT THE TIME OF JOINT INVESTIGATION

- e. Description of leak point (tick as applicable):
- | | | |
|--|---|--|
| <input type="checkbox"/> Drilled hole | <input type="checkbox"/> Hack saw cut | <input type="checkbox"/> Tear (_____), |
| <input type="checkbox"/> Complete Rupture | <input type="checkbox"/> Inward dent, | <input type="checkbox"/> Well head tampering |
| <input type="checkbox"/> Failed Weld-on illegal hot tap valve | <input type="checkbox"/> Failed Clamp, | <input type="checkbox"/> Missing Pipeline/Flowline |
| <input checked="" type="checkbox"/> Crude oil theft (illegal bunkering) point, | <input type="checkbox"/> Saver-pit over flow | <input type="checkbox"/> Third party tampering with Clamp |
| <input type="checkbox"/> Third party tampering with valve setting | <input type="checkbox"/> Bulging Outward | <input type="checkbox"/> Third party tampering with flange, |
| <input type="checkbox"/> Flare System/Bund wall failure | <input type="checkbox"/> Cold vent | <input type="checkbox"/> Surge vessel overflow, |
| <input type="checkbox"/> Valve Failure | <input type="checkbox"/> Relief valve failure | <input type="checkbox"/> Accidental 3 rd party equipment impact |
| <input type="checkbox"/> Others(specify) _____ | | |

- f. Incident caused by:
- Third party interference (Sabotage ; crude theft ; Line theft ; Accidental 3rd party damage
 Operational Others (including Mystery spills) _____

*This can be: a) Oil Spill b) Drilling fluid Chemical c) Situation d) construction e) Encroachment f) Fire,

JOINT INVESTIGATION REPORT

INCIDENT NO: 1796265 JIV report S/N: N^o 0000291

g. Spill point coordinates

h. Measuring unit

WGS 84

Northing:	Easting:
LATITUDE	LONGITUDE
4.94365	7.18480
 	
 	
 	

C. RISK ASSESSMENT

10. Type of environment:

- Land
 Swamp
 Water
 Seasonal swamp
 Shoreline/Waterfront

i. Type of environment to which oil has spread:

- Land
 Swamp
 Water
 River (identify) _____

ii. Weather condition

- Rain
 Sunny
 Dry
 Wet
 Windy
 Hot
 Cool

11. Distance from the nearest sensitive habitat

- Government reserved and designated protected area
- Drinking water source
- Built up area
- Farmlands
- Fish Farm/Pond
- Fishing net
- Others (specify). TARRE ROAD

[.m] }
 [.m] } NON SEEN
 [.m] }
 [.m] } WITHIN VICINITY
 [.m] }
 [.m] }

12. Containment measures put in place:

- Booms
 Trench
 Dyke
 Natural depression
 Pit
 None
- Others: _____

13. Any pictures or video coverage?

[N]

14. Further response/repair initiated as at the time of JIV?

[N]

If yes to item 14, give brief description:

REPAIR BY CLAMPING

15. Was there any disruption to the investigation?

[Y]

JOINT INVESTIGATION REPORT

INCIDENT NO: 1796265 JIV report S/N: N^o 0000291

If yes to item 15 give brief description:

NOT APPLICABLE

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

16. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
	NONE WITHIN AREA OF IMPACT				

17. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
	NONE WITHIN AREA OF IMPACT					

18. Fishing Nets/Fish Ponds


S/N	Nets/Ponds	Description	Quantity/Size	Comments
	NONE WITHIN AREA OF IMPACT			

19. Others (Specify) i.e. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
	NONE WITHIN AREA OF IMPACT			

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1)

A SECTION OF 12" IMORIVER - OGALE PIPELINE AT UMUDOLD SHOWING 1" VALVE CRUDE THEFT POINT INSTALLED AT 12 O'CLOCK POSITION BY UNKNOWN PERSONS.



JOINT INVESTIGATION REPORT

INCIDENT NO: 1796265 JIV report S/N: **Nº 0009291**

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

20. Impacted area boundary Coordinates (If more, Print and attach as an appendix)

WGS 84

S/N	Northing	LATITUDE	Easting	LONGITUDE
523		4.94364		7.18478
524		4.94367		7.18478
525		4.94370		7.18480
526		4.94375		7.18482
527		4.94382		7.18482
528		4.94384		7.18484
529		4.94371		7.18485
530		4.94346		7.18484
531		4.94344		7.18479
532		4.94342		7.18472
533		4.94344		7.18467
534		4.94346		7.18466
535		4.94249		7.18453
536		4.94350		7.18450
537		4.94352		7.18449
538		4.94358		7.18439
539		4.94360		7.18434
540		4.94361		7.18435
541		4.94356		7.18446
542		4.94352		7.18450
543		4.94348		7.18463
544		4.94348		7.18469
545		4.94348		7.18478
546		4.94353		7.18481

JOINT INVESTIGATION REPORT

N^o: 0000291

INCIDENT NO: 1796265 JIV report S/N:

G. INCIDENT INFORMATION:

a. Impacted Area Details

- Total calculated area of impact 0.0344
- Impact within R.O.W YES
- Impact outside R.O.W YES

b. Volume of oil recovered before completion of JIV (V_{rec}):

Recovered oil V_{rec} :	NIL	Barrels
---------------------------	-----	---------

Controlled recovery/evacuation from source with no impact to environment:

NIL	Barrels
-----	---------

c. Net Estimated Spilled Volume V_{Est} (bbls)* =

	14.39 BARRELS
Estimated Reported Volume** V_{rep} (bbls)=	15.0 BARRELS

***Notes:**

- Volume estimation was done using an excel based tool.(see attached for details on the calculation)
- Reported spilled volume is an estimate

Write other relevant notes taken into consideration for estimating the spilled in the box below:

/

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site: Conversion of m^3 to barrels is Volume (m^3) x 6.29; **Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of 1 bbl is rounded up to the next whole number.
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl ----- Reported volume = 16 bbl
 Calculated volume = 0.35 bbl ----- Reported volume = 0.4 bbl
 Calculated volume = 0.01 bbl ----- Reported volume = 0.1 bbl

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for volume estimation: record the calculation in a plain sheet of paper and attach to the JIV report

JOINT INVESTIGATION REPORT

INCIDENT NO: 1796265 JIV report S/N: N^o 000291

d. General Status of the site

- | |
|--|
| i. Joint investigation of the incident site found that there is no residual impact after the initial response and JIT therefore recommend that the site be closed out <input type="checkbox"/> |
| ii. Investigation of the incident site showed that there is residual impact on site requiring further works <input checked="" type="checkbox"/> |

e. Representatives

This report was filled, agreed and signed by the following joint investigation team representatives:

- Host Community:
- Department of Petroleum Resources (DPR):
- National Oil Spill Detection and Response Agency (NOSDRA):
- State Ministry of Environment (SME):
- Asset Owner:
- Signatories agree with reported findings:
- Separate DPR form has been filled out with same findings:

Tick as applicable

JOINT INVESTIGATION REPORT

INCIDENT NO: 1796265 JIV report S/N: **Nº 0090291**

f. Appendix 1: Overview sketch of the site

