

<u>Overview:</u> Part of spill impact on 8'' Saghara Tie-in-Saghara Manifold at Ugboegungun. Picture was taken during Joint Investigation of 20<sup>th</sup> November 2017.



<u>Close-up:</u> Hole due to corrosion on 8'' Saghara Tie-in-Saghara Manifold at Ugboegungun. Picture was taken during Joint Investigation of 20<sup>th</sup> November 2017.