



Close-up: Spill due to failed clamp on Cawthorne Channel Well 45T flowline at Mbiama. Picture taken during Joint Investigation of 13<sup>th</sup> August, 2011.